SITE ASSESSMENT GROUP CERCLIS DECISION RECORD

Site Name:	Howe Richa	rodson Sca	le Co (Fo.	mer)	
CERCLIS #:	VTD 00 207	8509	· · ·	·	
Site Assessme	nt Product Rev	iewed: P	A (S) 9-21-98	Other	
State Coordin	ator: (1) Do	n Sonth	·		9-28-98
SAG Reviewers	: (2) <u>Ma</u>	thenh Our	det	Date:	9/29/98
	(3)			Date:	
	(4)			Date:	
	٠.		•	•	
Recommended C	ERCLIS Decision	n :			· .
Reviewer (1) Reviewer (1) Reviewer (1) Reviewer (1) Reviewer (1)	(2) (3) (4) (2) (3) (4)	NFRAP - Los NFRAP - Ot! Defer to RO	Waste Croleum Only WRS Score her (Explain	Under Co	
Reviewer (1) Comments Revi		Concluded.			
Comments Revi	ewar (2):			·	
Comments Revi	ewer (3):				
Comments Feyi	-ver (4):				

SITE INSPECTION WORKSHEET

(Region I version 6/30/95)

WARNING!!

EPA has determined that the HRS score of any site that is progressing towards listing on the NPL is confidential. Deliberations regarding scoring or listing issues, the site specific status, and HRS scores cannot be released or discussed with non-Agency persons. For additional guidance see the April 30, 1993 OSWER Directive 9320, 1-11.

SITE/LOCATION

Site Name: Howe Richardson Scale Co. (former)

Street Address: 1 Scale Avenue

CERCLIS ID No.: VTD002078509

City: Rutland

State: VT

Zip Code:

Telephone:

05701

802-773-6251 Latitude: 43° 36' 2.0" N

Coordinates:

Longitude: 72° 58′ 30.0″ W

OWNER OPERATOR DENTIFICATION

Owner: Howe Center Ltd

Operator: Howe Center Ltd.

140 Granger Street Owner Address:

Operator Address: 140 Granger Street

City: Rutland

State: VT

Zip-Gode: 05701

*1*773-6**25**1

Zip Code:

05701

Telephone:

802-773-625

SITE EVALUATION

Agency/Organization/ WESTON/START TDD No.: 98-05-0035

Investigator: Mr. Pasquale Panza

Date: 21 September 1998

EPA CONTACT

EPA SAM: Mr. Donald Smith

JFK Federal Building Address

City: Boston

State: MA

Zip Code: 02203

Telephone: (617) **≾**73-9648

EPA Reviewer:

Date: 9-28-48

GENERAL INFORMATION

Site Description and Operational History: Provide a brief description of the site and its operational history. State the site name, owner, operator, type of facility and operations, size of property, active or inactive status, and years of waste generation. Summarize waste treatment, storage, or disposal activities that have or may have occurred at the site; note whether these activities are documented or alleged. Identify all source types and prior spills, floods, or fires. Summarize highlights of the PA and other investigations. Cite references


The Howe Richardson Scale Co. (former) (Howe) property is located at 1 Scale Avenue in Rutland, Rutland County, Vermont at coordinates 43° 36' 2.0" north latitude and 72° 58' 30.0" west longitude (Figure 1). The property is identified by the City of Rutland Tax Assessor's records as Tax ID No. 088033. The parcel is zoned as industrial and is bound by Moulthrop Avenue to the southeast, a business located at Porter Place to the south, a residence located on Park Street to the southwest, Moon Brook to the southwest, and by railroad tracks to the north, east, and west (Figure 2).

Howe was established in 1857 and had a 125-year history producing large industrial scales and balances at this location ending in 1982. Howe was formerly owned by PJD Inc., which is a subsidiary of Aerojet Investments Limited of Sacramento, California, and is no longer located on the subject property. The Howe property was on the real estate market from 1982 until Howe Center Ltd. (HCL) purchased the property in 1989. ACL is the current operator and is responsible for managing the property. HCL employs Giarcola Construction Corporation (GC) to perform maintenance, repair, and renovation activities on the property. GC renovated the existing buildings in 1989 for the purpose of leasing space to multiple tenants.

On 17 December 1984, a Prefiminary Assessment (PA) was conducted by NUS Corporation Field Investigation Team (NUS/FIT) at the Howe property. Howe is located on an 18-acre parcel of land near the center of Rutland. On the property, NUS/FIT observed approximately 20 buildings associated with the inactive plant. The area was restricted by a chain-link/barbed-wire fence. Moon Brook was also observed running through a portion of the property. The property is situated on generally flat terrain with the exception of steep slopes adjacent to Moon Brook. Although the former plant was closed, NUS/FIT observed a watchman at the front gate on Strongs Avenue.

NUS/FIT noted that 13 monitoring wells and one recovery well were installed by DuBois and King (DK) in 1980. Monitoring wells were placed at locations believed to be downgradient from an alleged solvent disposal area located near MW-4B. According to the Project Manager of GC and Vice President of HCL, Mr. Peter Giancola, this recovery well does not presently exist on site. This disposal area is associated with unspecified cleaning processes using chlorinated organic solvents that occurred in Building No. 16. The recovery well was installed as a response to a No. 6 fuel dil spill that occurred in 1979 from two underground storage tanks (USTs) of unspecified size located north of Building No. 11. Organic contaminants, primarily chlorinated solvents, have been detected consistently in groundwater samples collected from on-site monitoring wells.

Note: Text which appears in italics has been either copied or paraphrased from the NUS Corporation Field Investigation Feam Preliminary Assessment.





Additionally, the PA stated that the elevated land north of Moon Brook appeared to be a former landfill area used for the disposal of foundry ash/sand wastes. During a 1980 landfill investigation by DK, heavy metals such as lead,/chromium, and zinc we're found in groundwater. Wastes generated annually at the Howe facility from various processes are outlined in the following hazardous waste table.

1981 Hazardous Waste for Howe Richardson Scale Co. (former)

Hazardous Waste	Progess by Which Generated	Valume (Gallons per Year)
1,1,1-Trichloroethane Sludge	Immersion Degreasing	55
Paint Stripper - 80% Methylene Chloride	Paint Removal	110
15% Formic Acid		<u> </u>
Chromic Acid Solution, 3-10% by volume	Post-Plating Chromate Dip	165
Inhibited Hydrochloric Acid Solution, 30% by volume	Pre-Plating Acid/Dip	220
Sulfuric Acid Solution 17 by volume	Pre-Plating Asid Dip	. 55
Zinc Cyanide Plating Solution & Sludge	Electroplating	275
Nickel Plating Sludge	Nickel Plating	. 55
Coolants Cutting Qis	Machining Operations	660
Paint Thinners	Cleaning of Paint Spray Apparatus	660
Paint Filters & Paint Residue	Spray Painting	60.
Electro-Plating Wastewater	Electroplating, Chromating	1.25 x 10 ⁶
Lubricating & Hydraulic Oils	From Plant Machinery, and Vehicles	2,000
Alkaline Cleaners	Metals Cleaning prior to Painting, Plating and Heat Treatment.	6,000 :
Iron Phosphate Solution	Pre-Paint Phosphating of Metals	3,000

[24]

Roy F. Weston, Inc., (WESTON.) Superfund Technical Assessment and Response Team (START) personnel were unable to obtain additional information concerning waste listed in the 1981 hazardous waste table. Typically, cutting oils generally contain sulfur and chlorine [30]. Alkaline cleaners are generally composed of sodium hydroxide, carbonic acid, alkali metals (sodium and potassium), and alkali earth metals (calcium) [29; 30].

The plant was not certified as a hazardous waste treatment or disposal facility, but was permitted for temporary storage for up to 90 days. As of 31 December 1982, a complete cleanup and closure of the site was performed, consisting of the removal of stored wastes, decentamination of plant equipment, and subsequent waste disposal to an unknown location.

According to a 1986 Environmental Characterization (EC) investigation performed by Fluor Technology, Inc. Environmental Services (FT), following the removal of two No. 6 fuel oil USTs of unspecified sizes in 1980, 35 cubic yards (yd³) of contaminated soils were excavated in 1982 and a sump-pump-type oil recovery system was installed [1]. No further information was available to START personnel regarding the excavated contaminated soil. START personnel presume that these USTs are the same ones mentioned by NUS/FIT previously. This soil removal does not meet Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) requirements, due to the lack of analytical data following the removal. In October 1985, groundwater samples collected from the discharge pipe of the former recovery well system were analyzed for polychlorinated biphenyls (PCBs), volatile priority pollutants, heavy metals, "general minerals", and cyanide. These results indicated the presence of unspecified concentrations of organic compounds including benzene, ethyl benzene, chlorinated solvents, and total xylenes.

FT suspected that potential on site source areas of chlorinated organic solvents included a discharge pipe in the back of Building No. 16, a drain associated with the vapor degreaser formerly operated in the heat treat and plating room (Building No. 6), a chemical storage area beneath the brass room (Building No. 5), and a suspected surface disposal area in the vicinity of MW-4B. No additional information is available to START personnel regarding these potential sources. Additionally, the FT EC stated that personal interviews with former employees suggested that painting equipment was cleaned in the maintenance garage (Building No. 16).

Subsequently, quarterly groundwater monitoring has been conducted by ATC Environmental, Inc. (ATC) from 1989 to the present. Analytical results reveal that monitoring wells MW-4B, MW-30, MW-31D, MW-32S, MW-36D, MW-36D, and MW-37S continuously contain contaminants such as trichloroethylene, 1,1-trichloroethane, 1,1-dichloroethylene, and 1,1-dichloroethane.

On 16 October 1997, START personnel performed an on-site reconnaissance of the Howe property. Building No. 21 (Ruland News) is an automobile repair shop, which contained approximately four 55-gallon metal drums of virgin antifreeze, three 55-gallon drums of virgin automatic transmission fluid, and two 55-gallon metal drums of waste oil. The two waste oil drums were located inside the building on a concrete floor with no nearby floor drains and no signs of leakage [7].

START personnel observed two 275-gallon waste oil aboveground storage tanks (ASTs). One AST was located adjacent to Building No. 12 (Wolfsburg West Auto Service). This AST was situated on the ground without any secondary containment and approximately 10 feet (ft) from a catchbasin. The second AST was located behind Building No. 9 (Dave Nilsen Auto) and was situated on a concrete pad. Adjacent to the second AST on the ground was one empty 55-gallon metal drum, one scrap metal (automobile parts) 55-gallon metal drum, and one empty 55-gallon plastic drum marked "antifreeze". Adjacent to Building No. 17 was one plastic container with

approximately 100 gallons of waste grease/oil from the Howe Restaurant and Coffee Sing. This container was located on a small concrete pad with no signs of leakage [7]

Interstate Manufacturing Company (IMC), located in Building No. 11, machines titanium and aluminum metal. This process generates approximately one 55-gallon drum of waste coolant oil that is emptied annually by Safety Kleen Corporation. IMC had two machines that were situated inside a secondary containment apparatus. The apparatus consisted of a metal drain pan to prevent small amounts of leakage. Additionally, there were no drains in the concrete floor [7].

Hank's Auto Repair (Hank's), located in Building No. 16, contained two 55-gallon metal drums of antifreeze and one 55-gallon metal drum of waste oil. These drums were stored inside the building on a concrete floor and with no signs of leakage. Located in the center of the building, under the only car lift, was a floor drain. START presumes this drain redirects flow to a flush effluent pipe located in the rear (west) of Building No. 16. START personnel also presume that this effluent pipe is the discharge pipe mentioned in the FFEC. START personnel estimated that 8 square feet (ft²) of black, discolored soil was located near the effluent pipe [15]. A photoionization detector (PID) reading of 93 units above background levels within the first inch of soil was noted [7]. The depth of contaminated soil is unknown. There was stressed vegetation located near and advacent to the standed soil [7].

According to the Project Manager of GC and Vice President of HCL, Mr. Peter Giancola, following the START on-site reconnaissance, Hank's Auto Repair closed and Building No. 16 was leased to another automobile repair shop [43]. Mr. Giancola also stated that the floor drain and outlet (effluent) pipe were closed in place using cement grout. Mr. Giancola stated that regarding the floor drain "we will be contacting Mr. Charles Schwer of VT DEC regarding the stained area identified in the Braft SI report. We antisipate that we will work with VT DEC to remove soil in the stained area. It is likely that the soils will be poly-encapsulated on site in a secure area. The removal of these soils will be documented and reported to VT DEC" [43].

START personnel observed three 55-gallon drums adjacent to Building No. 9 inside an outdoor storage area for Newton Precast, Inc. The drums were approximately 100 feet south-southwest of Building No. 9. There was one empty metal drum, one metal drum labeled "surface consolidating agent", and one plastic drum presumed to contain sanding belt grit. No PID readings were noted near these drums. Near the three 55-gallon drums was a surface impoundment, which was approximately 15 feet wide by 30 feet long and used for disposal of daily concrete derived wastewater. Piles of concrete approximately 1 foot high formed the walls of the surface impoundment, which extended to a depth of approximately 2 feet below the ground surface. During the on-site reconnaissance, START personnel observed and photodocumented an employee of Newton Precast, Inc. disposing of approximately 50 gallons of concrete-derived wastewater to this surface impoundment. No PID readings were noted within this surface impoundment [7].

Building No. 22 was surrounded on two sides (south and west) by scrap metal piles. Included with this scrap metal was one rusted tank. START personnel were informed by Mr. Peter

Giancola, that this tank was a former water boiler tank. No PID readings were noted with this tank [7].

The southern portion of the Howe property was littered with slag debris. Discolored soil, stressed vegetation, or no vegetation were observed on the southwestern portion of the property. There was no PID reading associated with the discolored soil near MW-78. Similarly stained soils were located on the slope between Moon Brook and MW-37S. According to Mr. Peter Giancola, the discolored soil (burnt sand) and slag are part of the former landfill [7].

START personnel were unable to uncover a drain located in Building No. 6 (White Rocks Printing). Mr. Joseph Giancola owner of GC, presumes this drain was associated with the drain for the vapor degreaser mentioned by the KT EC. Mr. Joseph Giancola also stated that (an unspecified number of) other drains in this building were removed by tenants during renovations.

There was no evidence of the former chemical storage area, located in the basement of Building No. 5, as mentioned by the FT EC. Green Mountain Bottle Recycling Redemption currently occupies this location to provide storage for bottles and cans. Containment features for this former designated chemical storage area include concrete floors and concrete walls. START observed that the concrete floor was in good condition with no cracks, floor drains, or staining noted.

Six of the 16 monitoring wells located on the Howe property were opened. START personnel obtained a PID reading of 2.1 units above background levels from MW-32S. No other PID readings were recorded from the remaining live monitoring wells.

During the START on-site reconnaissance, the businesses within the Howe complex were toured. The businesses were characterized as retail, office-related, restaurant, and small commercial businesses. No other source areas were noted except for those described above. Several of the businesses were noted to maintain various quantities of products such as household cleaners, paints, roofing tar, and harcare products. Automotive oils, fluids, and cleaning agents were observed to be stored and used as part of automobile repair businesses located on the property. These materials were observed by START personnel to be properly maintained within the respective businesses and were not evaluated as part of this assessment. Table 1 provides a list of the tenants occupying the facility during the on-site reconnaissance and a brief description of START observations.

Tenants Located on the Howe Richardson Scale Co. (former) Property

Building No. Tenant Description 2 Atomic Pro Audio Productions 3 Awesome Graphics 3 Awesome Graphics 3 Castleton State College 3 The Frankin Conference Center 3 Howe Center Hair Trends Ltd. 4 Howe Restaurant & Confee Shop 3 Jones, Candy Massage Therapy 3 Merkel Associates 3 Merkel Associates 4 None 5 State of Wernsom Dept. Human Services 3 Home Recogny Offices 4 None 5 Orfices 7 None 6 A Stitch in Timy 6 Lucent Jechnologies 6 White Rock Popting 6 Vermant Depchaltris, Survivors, Inc. 7 None 8 North American Van Lines			
2 Carpet Warehouse, Inc. 3 Awesome Graphics 3 Castleton State College 4 Capter Storage 5 Capter Storage 6 Capter Storage 7 Capter Storage 7 Capter Storage 8 Castleton State College 9 Castleton State College 10 Castleton State College 11 Castleton State College 12 Capter Storage 13 Castleton State College 14 Conference Royms 15 Conference Royms 16 Castleton State College Shop 17 Conference Royms 18 Castleton State College Shop 18 Castleton Royms 19 College 10 Castleton State College Shop 10 College 10 Castleton Royms	Building No.	Tenant	Rescription
Awesome Graphics Castleton State College The Franklin Conference Center Conference Rooms The Franklin Conference Center T	2	Atomic Pro Audio Productions	Offices
Castleton State College The Franklin Conference Center The Franklin Conference Supported Suppo	2	Carpet Warehouse, Inc.	Capper Storage
3 Howe Center Hair Trends Ltd. Hair Dresser 3 Howe Restaurant & Settge Shop. Restaurant/Coffee Shop 3 Jones, Candy Message Therapy 3 Merkel Associates 3 Omega Electric Construction Co., Ing. 3 Rutland City Schools 4 Classrooms/Offices 3 UVM Extension System 5 Orfices 4 None 5 Oreen Mountain Bottle Recycling Redemption 6 A Stirch in Time 5 Sewing Shop 6 Lucent Jechnologies 6 Miss Jackies School of Dance 6 White Rocks Pruting 7* None Vacant 8 North American Van Lines 9 Nilsen, David Auto, Inc. 10 Hipwe Outlet Warehouse Grocery Grocery Store	3	Awesome Graphics	Graphics Designs Studio
3 Howe Center Hair Trends Ltd. Restaurant/Coffee Shop 3 Jones, Candy. Massage Therapy Offices 3 Merkel Associates Classrooms/Offices 3 Omega Electric Construction Co., Inc. 3 Rydang City Schools Classrooms/Offices Classrooms/Offices 3 Live of Wernon, Dept. Human Services Offices 3 UVM Extension System Offices 4 None Vacant Creen Mountain Bottle Recycling Rydemption Sewing Shop Charles Schools of Dance Dance Floor/Offices 6 Miss Jackies Schools of Dance Dance Floor/Offices 6 White Rocks Printing Offices Offices None Vacant Storage Vacant Offices Offices Offices Offices Swing Shop Offices Offices Swing Shop Charles Schools of Dance Offices	3	Castleton State College	Classrooms/Offices
3 Howe Restaurant & Soffce Shop 3 Jones, Candy - Message Therapy 3 Merkel Associates 3 Omega Electric Construction Co., Inc. 3 Ruland Gity Schools 3 State of Vermon, Dept. Human Services 4 None 5 Orden Mountain Bottle Recycling Redemption 6 A Stitch in Time 6 A Stitch in Time 6 Miss Jackies School of Dance 6 White Rocks Protting 6 Vermont Psychiatris Survivors, Inc. 7 None 7 None None None Vacant Storage Offices 6 White Rocks Protting Offices 7 None None Vacant Storage A Storage A Stitch in Time Sewing Shop Offices Offices Offices Storage A Storage Ploor/Offices Offices Offices Automobile Repair Offices Nilsen, David Auto, Inc. Automobile Repair Officery Store	3	The Franklin Conference Center	Conference Rooms
3	3	Howe Center Hair Trends Ltd.	Mair Dresser
3 Merkel Associates Schools Offices 3 Omega Electric Construction Co., Ing. 3 Rydand Gity Schools Classrooms/Offices 3 Rydand Gity Schools Classrooms/Offices 3 Elate of Vermon Dept. Human Services Offices 3 UVM Extension System Offices 3 Home Security/Office/Attic Storage Storage 4 None Vacant 5 Owen Mountain Bottle Recycling Rydemption Bottle Storage 6 A Stitch in Time Sewing Shop 6 Lucent Pechnologies Offices 6 Miss Achies School of Dance Dance Floor/Offices 6 White Rocks Printing Offices 6 Vermont Psychiatrits Survivors, Inc. Offices 7* None Vacant 8 North American Van Lines Storage/Warehouse 9 Nilsen David Auto, Inc. Automobile Repair 10 Howe Outlet Warehouse Grocery Grocery Store	3	Howe Restaurant & Coffee Shop	Restaurant/Coffee Shop
3 Omega Electric Construction Co., Inc. 3 Rydland City Schools Classrooms/Offices 3 State of Wernfort, Dept. Human Services Offices 3 UVM Extension System Offices 3 Home SecretivyOffice/AtticStorage Vacant None Vacant Survices Mountain Bottle Recycling Redemption Sewing Shop Lucent Technologies Miss Actrics School of Dance Dance Floor/Offices Miss Actrics School of Dance Offices White Rocks Printing Offices Vermont Psychiatris Survivors, Inc. Offices None Vacant None Vacant Automobile Repair Hibwe Outlet Warehouse Grocery Grocery Store	3	Jones, Candy - Massage Therapy	Officer
3 Rudand Gity Schools 3 State of Vernors, Dept. Human Services Offices 3 UVM Extension System Offices 3 Home Secucity/Office/Attic Storage Storage 4 None Vacant 5 Oreen Mountain Bottle Recycling Redemption Bottle Storage 6 A Stitch in Time Sewing Shop 6 Lucent Technologies/Offices 6 Miss Jackies School of Dance Dance Floor/Offices 6 White Rocks Protting Offices 7* None Vacant 8 North American Van Lines Storage/Warehouse 9 Nilsen David Auto, Inc. Automobile Repair 10 Howe Outlet Warehouse Grocery Grocery Store	3	Merkel Associates	Classrooms/Offices
3 State of Vernon Dept. Human Services Offices 3 UVM Extension System Offices 3 Home Security/Office/Attic Storage Storage 4 None Vacant 5 Orden Mountain Bottle Recycling Redemption Bottle Storage 6 A Stitch in Time Sewing Shop 6 Lucent Technologies Offices 6 Miss Lackies School of Dance Dance Floor/Offices 6 White Rocks Printing Offices 7* None Vacant 8 North American Van Lines Storage/Warehouse 9 Nilsen David Auto, Inc: Automobile Repair 10 Howe Outlet Warehouse Grocery Grocery Store	3	Omega Electric Construction Co., Inc.	Offices
3 UVM Extension System Offices 3 Home Security/Office/Attic Storage Storage 4 None Vacant 5 Oricen Mountain Bottle Recycling Redemption Bottle Storage 6 A Stitch in Time Sewing Shop 6 Lucent Technologies Offices 6 Miss Ackies School of Dance Dance Floor/Offices 6 White Rocks Printing Offices 7* None Vacant 8 North American Van Lines Storage/Warehouse 9 Nilsen David Auto, Inc. Automobile Repair 10 Howe Outlet Warehouse Grocery Grocery Store	3	Rydang City Schools	Classrooms/Offices
3 Home Security Office/Attic Storage Storage 4 None Vacant 5 Oreen Mountain Bottle Recycling Redemption Bottle Storage 6 A Stitch in Time Sewing Shop 6 Lucent Technologies Offices 6 Miss Tackies School of Dance Dance Floor/Offices 6 White Rocks Protting Offices 7* None Vacant 8 North American Van Lines Storage/Warehouse 9 Nilsen David Auto, Inc. Automobile Repair 10 Howe Outlet Warehouse Grocery Grocery Store	3	State of Vermont, Dept. Human Services	Offices
4 None Vacant 5 Green Mountain Bottle Recycling Redemption Bottle Storage 6 A Stitch in Time Sewing Shop 6 Lucent Technologies Offices 6 Miss Jackies School of Dance Dance Floor/Offices 6 White Rocks Printing Offices 6 Vermont Psychiatris Survivors, Inc. Offices 7* None Vacant 8 North American Van Lines Storage/Warehouse 9 Nilsen David Auto, Inc. Automobile Repair 0 Howe Outlet Warehouse Grocery Grocery Store	. 3	UVM Extension System	Offices
5 Oreen Mountain Bottle Recycling Redemption Bottle Storage 6 A Stitch in Time Sewing Shop 6 Lucent Technologies Offices 6 Miss Jackies School of Dance Dance Floor/Offices 6 White Rocks Printing Offices 6 Vermont Psychiatris, Survivors, Inc. Offices 7* None Vacant 8 North American Van Lines Storage/Warehouse 9 Nilsen Dawid Auto, Inc: Automobile Repair 0 Howe Outlet Warehouse Grocery Grocery Store	3	Home Security/Office/Attic Storage	Storage
6 A Stitch in Time Sewing Shop 6 Lucent Technologies Offices 6 Miss Fackies School of Dance Dance Floor/Offices 6 White Rocks Printing Offices 6 Vermont Psychiatris Survivors, Inc. Offices 7* None Vacant 8 North American Van Lines Storage/Warehouse 9 Nilsen David Auto, Inc. Automobile Repair 0 Howe Outlet Warehouse Grocery Grocery Store	4 (None	Vacant ·
6 Lucent Technologies Offices 6 Miss Jackies School of Dance Dance Floor/Offices 6 White Rocks Printing Offices 6 Vermont Psychiatris Survivors, Inc. Offices 7* None Vacant 8 North American Van Lines Storage/Warehouse 9 Nilsen David Auto, Inc. Automobile Repair 0 Howe Outlet Warehouse Grocery Grocery Store	3	Oreen Mountain Bottle Recycling Redemption	Bottle Storage
6 Miss Jackies School of Dance Dance Floor/Offices 6 White Rocks Printing Offices 6 Vermont Psychiatris Survivors, Inc. Offices 7* None Vacant 8 North American Van Lines Storage/Warehouse 9 Nilsen David Auto, Inc. Automobile Repair 0 Howe Outlet Warehouse Grocery Grocery Store	6	A Stitch in Time	Sewing Shop
6 White Rocks Printing Offices 6 Vermont Psychiatris Survivors, Inc. Offices 7* None Vacant 8 North American Van Lines Storage/Warehouse 9 Nilsen David Auto, Inc. Automobile Repair 0 Howe Outlet Warehouse Grocery Grocery Store	6	Lucent Technologies	Offices
6 Vermont Psychiatris, Survivors, Inc. Offices 7* None Vacant 8 North American Van Lines Storage/Warehouse 9 Nilsen Dawid Auto, Inc. Automobile Repair 0 Howe Outlet Warehouse Grocery Grocery Store	6	Miss Jackies School of Dance	Dance Floor/Offices
7* None Vacant 8 North American Van Lines Storage/Warehouse 9 Nilsen Dawd Auto, Inc. Automobile Repair 0 Howe Outlet Warehouse Grocery Grocery Store	. 6	White Rocks Printing	Offices
8 North American Van Lines Storage/Warehouse 9 Nilsen David Auto, Inc. Automobile Repair 0 Howe Outlet Warehouse Grocery Grocery Store	6	Vermont Psychiatris Survivors, Inc.	Offices
9 Nilsen Dawd Auto, Inc. Automobile Repair 0 Howe Outlet Warehouse Grocery Grocery Store	7* (None	Vacant
0 Howe Outlet Warehouse Grocery Grocery Store	8	North American Van Lines	Storage/Warehouse
	<u> </u>	Nilsen David Auto, Inc	Automobile Repair
	0	Howe Outlet Warehouse Grocery	Grocery Store
None (Third Floor) Storage	J lb	None (Third Floor)	Storage
11 Berkshire Armored Car Offices/Garage	11	Berkshire Armored Car	Offices/Garage
Interstate Mfg. Co. Machine Shop		Interstate Mfg. Co.	Machine Shop

Tenants Located on the Howe Richardson Scale Co. (former) Property (Concluded)

Building No.	Tenant /	Description
11	Newton Precast, Inc. DBA The Step Shop	Cement Casters
11	Phillips, Roderick K	Bukery
11	Jerry LeBlonde Photiques	Offices
11	Rutland Plywood Copporation	Storage/Warehouse
12	Hart, J&J - Wolfsburg West Auto Service (Northeast corner of the building)	Automobile Repair/Parts
12	None (remainder of the building)	Vacant
13	Vermont Candy Wreaths, Inc.	Wreath Production
13	Basement of Vermont Capity Wreaths	Storage
14	Southwestern Vermont Council on Aging	Offices
14	Vermont Associates for Training & Development	Offices
15	Al Melanson Co., Inc.	Offices
15	R & D Machinery, Inc	Unknown
16*	Hank's Auto Repair	Automobile Repair
y/ <	Booth Dental Laps, Inc.	Produce False Teeth
18	Aronson & Okon, Inc. Surveyors	Offices
18	Day Associates Inc.	Offices
18	Network Services Corp.	Offices
.18	Progressive Qesign, Inc.	Offices
18	Commonity Access Program of Rutland County	Offices
19	None	Vacant
20	None	Vacant
21	Runand News Company	Automobile Repair
24	None .	Storage Warehouse (GC)

[5; 7]

* = Indicates the following changes that occurred after the START on-site reconnaissance: Building No. 16 is occupied by Mighty Muffler (Automobile Repair) and Building No. 7 by Fastenal, (Retail/Wholesale Sales).

SOURCE EVALUATION

Description of each Source: Identify each source area by name and number, and classify each source into a source type category (see SI Table 1). Describe the dimensions of each source. Identify the hazardous substances associated with each source. Determine the containment characteristics for each source by pathway (see HRS Tables 3-2, 4-2, 6-3 and 6-9).

1. Effluent Pipe (Other)

FT suspected that potential on-site source areas of chlorinated organic solvents included a discharge pipe in the back of Building No. 16. Additionally, the FT EC stated that personal interviews with former employees suggested that painting equipment was cleaned in the maintenance garage (Building No. 16)

START personnel observed a floor drain, focated under a car lift, in Building No. 16. START personnel presume that this drain redirects flow to a flush effluent pipe located in the rear (west) of Building No. 16. START personnel also presume that this effluent pipe is the discharge pipe mentioned in the FT EC. For the purpose of this investigation, this source will be evaluated as available to all pathways.

2. Contaminated Soil (Contaminated Soil)

Approximately 8 ft of black, discolored soft was located near the effluent pipe [15]. Groundwater levels in the vicinity (at monitoring well PZ-1B) of the effluent pipe average 6 feet below ground surface. The volume of contaminated soil is estimated at 48 cubic feet (ft³), presuming the contaminated soil extends to the groundwater level [6; 15]. There was a PID reading of 93 units above background levels within the first inch of soil [7]. Stressed vegetation was noted near and adjacent to the stained soil. For the purpose of this investigation, this source will be evaluated as available to all pathways.

3. Landfill (Landfill)

The PA stated that the elevated land north of Moon Brook appeared to be a former landfill area for disposal of foundry ask/sand wastes. START personnel observed that the southern portion of the property was littered with slag debris. Discolored soil and stressed vegetation were located on the southwestern portion of the property. Similarly stained soils were located on the slope between Moon Brook and MW-37S. According to Mr. Peter Giancola, the discolored soil (burnt sand) and slag are part of the former landfill. No PID readings were associated with the discolored soil near MW-7B.

Assuming the southern portion of the property to be the former landfill, START personnel estimated an area of 403,137 ft² [17]. Utilizing a structure contour map of landfill/native soil contact sketch by FT depth of landfill material averages 11.5 ft, resulting in a volume of 4,636,076 ft³. In addition, based on available file information, there exists a disposal area south of Building No. 16 and adjacent to the landfill. These sources will be evaluated as one potential source available to all pathways.

4. Drums (Drums)

START personnel observed three 55-gallon drums adjacent to Building No. 2 inside an outdoor storage area for Newton Precast, Inc. The drums were approximately 100 feet south-southwest of Building No. 9. There was one empty instal drum, one metal drum labeled "surface consolidating agent", and one plastic drum presumed to contain sanding belt grit. For the purpose of this investigation, two 55-gallon drums will be evaluated as available to all pathways.

5. Aboveground Storage Tank (Tank)

A 275-gallon waste oil AST was located adjacent to Building No. 12 (Wolfsburg West Auto Service). This AST was situated on the ground without any secondary containment and approximately 10 feet from a catchbasin. For the purpose of this investigation, this source will be evaluated as available to all pathways.

6. Aboveground Storage Tank (Tark)

Another 275-gallon waste oil AST was located behind Building No. 9 (Dave Nilsen Auto) and situated on a concrete pad. For the purpose of this investigation, this source will be evaluated as available to all pathways.

7. Non-Drum Container (Non-Drum Container)

One plastic containing approximately 100 gallons of waste grease/oil from the Howe Restaurant and Coffee Shop was located adjacent to Building No. 17. For the purpose of this investigation, this source will be evaluated as available to all pathways.

8. Surface Impoundment (Surface Impoundment)

A lagoon approximately 15 feet wide by 30 feet long was located near Building No. 9. During the on-site reconnaissance, an employee of Newton Precast, Inc. disposed of approximately 50 gallons of concrete-derived wastewater to this surface impoundment. For the purpose of this investigation, this source will be evaluated as available to all pathways.

9. Contaminated Soil (Contaminated Soil)

According to a 1986 EC investigation performed by FT, following the removal of two No. 6 fuel oil USTs of inspecified sizes in 1980, 35 yd³ of contaminated soils were excavated in 1982 and a sump-pump-type oil recovery system was installed [1]. No further information is available regarding the excavated contaminated soil. START personnel presume that these USTs are the ones mentioned by NUS/FIT previously. This soil removal does not meet CERCLA requirements, due to the lack of analytical data following the removal. For the purpose of this evaluation, since this area is located beneath asphalt, this contaminated soil is only available to the groundwater and surface water pathways.

10. Drums (Drums)

Building No. 21 (Rutland News) is an automobile repair shop, which contained approximately four 55-gallon metal drums of virgin antifreeze, three 55-gallon drums of virgin automatic transmission fluid, and two 55-gallon metal drums of waste oil. These drums are located inside the building on a concrete floor with no nearby floor drains and no signs of leakage. For the purpose of this evaluation, only the two waste oil drums will be evaluated and are available to the air pathway only.

11. Drums (Drums)

Hank's, located in Building No. 16, contained two 55 gallon metal drums of antifreeze and one 55-gallon metal drum of waste oil. These drums were stored inside the building on a concrete floor and with no signs of leakage. For the purpose of this investigation, only one 55-gallon waste oil drum will be evaluated as available to the air pathway.

12. Drums (Drums)


IMC, located in Building No. 11, machines titanium and aluminum metal. This process generates approximately one 53-gallon drum of waste coolant oil that is emptied annually by Safety Kleen Corporation. There were no drains in the consrete floor. For the purpose of this investigation, this 55-gallon drum will be evaluated as only available to the air pathway.

13. Drain (Other)

Due to carpeting, START personnel were unable to assess the condition of the Building No. 6 floor drain (White Rocks Printing). Mr. Joseph Giancola presumes this drain to be associated with the drain for the vapor degreaser mentioned by the FT EC. Mr. Joseph Giancola also stated that (an unspecified number of) other drains in this building were removed by tenants. For the purpose of this investigation, this source will no longer be evaluated.

14. Chemical Storage Area (Non-Drum Containers)

There was no evidence of the former chemical storage area, located in the basement of Building No. 5, mentioned by the FT EC. Green Mountain Bottle Recycling Redemption currently resides at this location to provide storage for bottles and cans. Containment features for this former designated chemical storage area include concrete floors and concrete walls. START observed that the concrete floor was in good condition with no cracks, floor drains, or staining noted. For the purpose of this investigation, this source will not be evaluated.



According to the FT EC, following the removal of two USTs (1980) known to have leaked No. 6 fuel oil, contaminated soils were excavated and a sump-pump-type oil recovery system was installed. Fuel oil is ineligible under CERCLA investigations; this source will not be further evaluated.

<u> </u>		\sim			
	. / /		Pathway	Availability	
Source No.	Source Type	GW	SW	✓ _{SE}	A
1	Other (effluent pipe)	/Y		Y	Υ
. 2	Contaminated Sol	7 (<u></u>	Y	Y
3	Landfill	/ÿ\	X	Y	Y
4	Drugas	$//_{Y}$	\searrow	Y	Y
. 5	Tank	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	$//_{Y}$	Υ	Y
6	Tank	$\sum_{\mathbf{Y}}$	/ Y	Y	Υ
7	Non-Drum Container		Y	Y	Y
8	Surface Impoundment) y	Υ	Υ	Y
	Contaminated Soil	V /	Y	N	N
10	Drums	N	N	N	Y
- 11	Drums	N	N	N_	Y
12	Drums/	N	Ň	N	Y
13	Other	N	N	N	N
14	Non-Drum Containers	N	N	N	N
15	Tanks	I	I	1	I

Legend: Y = available to pathway

N = not available to pathway

availability anknown

= ineligible waste

None of the sources had sufficient information to evaluate on Tier A Hazardous Constituent Quantity) or Tier B (Hazardous Wastestream Quantity).

1. Effluent Pipe (Other)

Tier C (Volume)

START assumes the distance between the floor drain and end of the effluent pipe is approximately 15 feet [7]. Assuming a diameter of 4 inches, START personnel estimated the effluent pipe has a volume of 1.3 cubic feet [31]. For multiple source properties, the total volume (in ft³) is divided by 67.5.

$$1.3 \text{ ft}^3 \div 67.5 = 0.019$$

Tier D (Area)

This source cannot be evaluated on this tier.

Source 1 WQ = 0.019

2. Contaminated Soil (Contaminated Soil)

Tier C (Volume)

Groundwater in the vicinity (PZ-IR) of the contaminated soil averages 6 feet. Presuming the contaminated soil approximately 8 ft³ extends to the groundwater level, then the volume of contaminated soil is estimated at 48 ft³. For multiple source properties, the total volume (in ft³) is divided by 67,500.


$$48 \text{ ft}^3 \div 67,500 = 0.0007$$

Tier D (Area)

Approximately 8 ft² of discolored soil is located adjacent to an effluent pipe on the west side of Building No. 16. For multiple source properties, the total area for contaminated soil (in ft) is divided by 34,000

$$\beta \text{ ft}^2 / 34 |000| = 0.0002$$

Source 2 WQ = 0.0007



3. Landfill (Landfill)

Tier C (Volume)

An estimated 4,636,076 ft³ of landfill material is located on the southern portion of the property. For multiple source properties, the total volume for the landfill (an ft³) is divided by 67,500.

$$4,636,076 \text{ ft}^3 \div 67,500 = 68.68$$

Tier D (Area)

The landfill covers an area of approximately 403,137 ft². For multiple source properties, the total area (in ft²) for the landfill is divided by 3,400

$$403,137 \text{ ft}^2 \div 3,400 = 118.57$$

Source 3 WQ = 118.57

4. Drums (Drums)

Tier C (Volume)

There are two 55-gallon drums located approximately 100 feet southwest of Building No. 9. For multiple source properties, the total number of drums is divided by 10.

2 drums
$$\Rightarrow$$
 10 = 0.2

Tier D (Area)

This source cannot be evaluated on this tier.

Source 4 WQ = 0.2

5. Aboveground Storage Tank (Tank)

Tier C (Volume)

A 275-gallon waste oil AST was located adjacent to Building No. 12 (Wolfsburg West Auto Service). For multiple source properties, the total volume of the tank in gallons is divided by 500.

$$205 \text{ gallons} \div 500 = 0.55$$

Tier D (Area)

This source cannot be evaluated on this tier.

Source 5 WQ = 0.55

6. Aboveground Storage Tank (Tank)

Tier C (Volume)

Another 275-gallon waste oil AST was located behind Building No. 9. For multiple source properties, the total volume of the tank in gallons is divided by 500.

$$275 \text{ gallons} \div 500 = 0.55$$

Tier D (Area)

This source cannot be evaluated on this tier.

Source 6 WQ = 0.55

7. Non-Drum Container (Non-Drum Container)

Tier C (Volume)

A 100-gallon container of waste grease/oil was located near Building No. 17. For multiple source properties, the total volume of the container in gallons is divided by 500.

100 gallons
$$\div$$
 500 = 0.2

Tier D (Area)

This source cannot be evaluated on this tier.

Source 7 WQ = 0.2

8. Surface Impoundment (Surface Impoundment)

Tier C (Yolume)

A lagoon surrounded with concrete located near Building No. 9 consists of approximately (15 ft \times 30 ft \times 2 ft) 900 ft of liquid. For multiple source properties, the total volume for the surface impoundment is divided by 67.5.

$$900 \text{ ft} \div 67.5 = 13.33$$



The lagoon covers an area of approximately 450 ft. For multiple source properties, the total area (in ft²) for the surface impoundment is divided by 13.

$$450 \text{ ft}^2 \div 13 = 34.62$$

Sourge 8 WQ = 34.62

9. Contaminated Soil (Contaminated Soil)

Tier C (Volume)

Thirty-five yd³ of contaminated soils were excavated in 1982 as a response to leakage from two No. 6 fuel oil USTs. For multiple source properties, the total volume for the contaminated soil (in yd³) is divided by 2,500.

$$35 \text{ yd}^3 \div 2,500 = 0.014$$

Tier D (Area)

Insufficient information is available to evaluate the source on this tier.

Source 9 WQ = 0.014

10. Druns (Drums)

Tier C (Volume)

There are two 55-gallon waste oil drums located in Building No. 21. For multiple source properties, the total number of drums is divided by 10.

2 drums
$$= 10 = 0.2$$

Tier D (Area)

This source cannot be evaluated on this tier.

Source 10 WQ = 0.2



Tier C (Volume)

There is one 55-gallon drum located in Building No. 16. For multiple source properties, the total number of drums is divided by 10.

$$1 \text{ drums} \div 10 = 0.1$$

Tier D (Area)

This source cannot be evaluated on this tier.

Source 11 WQ = 0.1

12. Drums (Drums)

Tier C (Volume)

There is one 55-gallon drum located in Building No. 11. For multiple source properties, the total number of drums is divided by 10.

$$1 \text{ drams} \div 10 = 0.1$$

Tier D (Area)

This source cannot be evaluated on this tier.

Source 12 WQ = 0.1

Sources 13 through 15 are ineligible or not available to any pathways. For the following pathways, sources 1 through 9 have a site waste quantity total of (0.019 + 0.0007 + 118.57 + 0.2 + 0.55 + 0.55 + 0.2 + 34.62 + 0.014) = 154.7. From SI Table 2, a site WQ total between 100 and 10,000 is assigned an Hazardous Wastestream Quantity (HWQ) of 100. These sources are available to the groundwater and surface water pathways.

GW HWQ = 100

SW HWQ = 100

SOURCE EVALUATION (Concluded)


For the following pathway, sources 1 through 8 have a site waste quartity total of (0.019 + 0.0007 + 118.57 + 0.2 + 0.55 + 0.55 + 0.2 + 34.62) = 154.7. From SI Table 2, a site WQ total between 100 and 10,000 is assigned an HWQ of 100. These sources are available to the soil exposure pathway.

SE HWQ = 100

For the following pathway, sources 1 through 8 and 10 through 12 have a site waste quantity total of (0.019 + 0.0007 + 118.57 + 0.2 + 0.55 + 0.55 + 0.2 + 34.62 + 0.2 + 0.1 + 0.1) = 155.1. From SI Table 2, a site WQ total between 100 and 10,000 is assigned an HWQ of 100. These sources are available to the air pathway.

AIR HWQ = 100

Notes: If sources 1,2, and 11 associated with Building No. 16 were not evaluated, this would result in a decrease in WQ score of 0.0197 for the groundwater, surface water, and soil exposure pathways. The WQ score for the Air pathway would decrease by 0.1197. These results will not change the HWQ score of 100.



CERCLIS No. VTD002078509

SUTABLE 1: HAZARDOUS WASTE QUANTITY (HWQ) SCORES FOR SINGLE SOURCE SITES AND FORMULAS FOR MULTIPLE SOURCE SITES

	SOURCE SI	IIES ·	<u> </u>	·		
			Single Source (assigned HWC		-	Multiple Source Sites
Tier	Source Type	HWQ = 10	HWQ = 100	HWQ = 10,000	HWQ = 1,000,000	Divisors for Assigning Source WQ Values
A Hazardous Constituent Quantity	· N/A	HWQ = 1 if Hazardous Constituent Quantity data are complete HWQ = 10 if Hazardous Constituent Quantity data are not complete	> 160 to 10,000 lp/s	> 10,000 to 1 Trillion lbs	> 1 million lbs	lbs ÷ 1
B Hazardous Wastestream Quantity	N/A	≤500,000 lbs	> 500,000 to 50 million lbs	50 million to 5 billion lbs	>> hallion this	lbs ÷ 5,000
	Landfill	≤6.75 million ft³ ≤250,000 yd³	> 6.75 million to 675 million ft ³ > 250,000 to 25 million yd	>675 million to 67.5 billion ft ³ >25 million to 2.5 billion yd ³	>67.5 billion ft ³ >2.5 billion fd ³	$p \text{ ft}^3 \div 67,500$ $p \text{d}^3 \div 2,500$
	Surface impoundment	≤6,750 ft ³ ≤250 yd ³	> 6,750 to 675,000 ft ³ > 250 to 25,000 yd ³	>075,000 to 67.5 million 763 25,000 to 2 5 million yd ³	>67.5 million ft ³ >2.5 million yd ³	$ft^3 \div 67.5$ yd ³ ÷ 2.5
	Drums ·	≤1,000 drums	>1,000 to 100,000 drums	> 100,000 to 0 million drums	> 10 million drums	drums ÷ 10
C Volume	Tanks and	≤50,000 gallons	>50,000 to 5 million gallons	>5 million to 500 million gallons	500 million gals.	gallons + 500
, oranic	containers		:			<u> </u>
	Contaminated soil	≤6.75 million ft³ ≤250,000 yd³	>6.75 million to 675 million ft ³ >250,000 to 25 million yd ³	>675 million to 67.5 billion ft ³ >25 million to 2.5 billion yd ³	> 67.5 billion ft ³ 2.5 billion y t ³	$d^3 \div 67,500$ $d^3 \div 2,500$
	Pile	≤6,750 ft³ ≤250 yd³	>6,750 to 675,000 ft ³ >250 to 25,000 yd ³	> 675,000 to 67.5 million ft ³ > 25,000 to 2.5 million yd ³	> 67.5 million 18 ³ > 2.5 million yd ³	$\begin{cases} ft^3 + 67.5 \\ yd^3 + 2.5 \end{cases}$
	Other	≤6,750 ft³ ≤250 yd³	>6,750 to 675,000 ft ³ >250 to 25,000 yd ³	> 675,000 to 67.5 million ft ³ > 25,000 to 2.5 million yd ³	>67.5 million ft ³ >2.5 million yd ³	ft ÷ 67.5 yd ÷ 2.5

SI TABLE 1: HAZARDOUS WASTE QUANTITY (HWQ) SCORES FOR SINGLE SOURCE SITES AND FORMULAS FOR MULTIPLE SOURCE SITES

			Single Source (assigned HW)			Multiple Source Sites
Tier	Source Type	HWQ = 10	HWQ = 100	HWQ = 10,000	HWQ = 1,000,000	Divisors for Assigning Source WQ Values
	Sandfill	/340,000 ft ≤7.8/adres	> 340,000 to 34 million ft ² > 7.8 to 780 acres	34 million to 3.4 bil. ft ² > 780 to 78,000 acres	>3.4 billion ft ² >78,000 acres	$ft^2 \div 3,400$ acres ÷ 0.078
	Surface Impoundment	\$1,300 ft² ≤0.029 acres	>1,300 to 130,000 ft ² 0.029 to 2.9 acres	>130,000 to 13 million ft ² >2.9 to 290 acres	> 13 million ft ² > 290 acres	ft ² ÷ 13 acres ÷ 0.00029
D Area	Contaminated Soil	≤3.4 million fr ≤78 acres	3.4 million to 340 million hi ² > 78 to 7,800 acres	340 million to 34 bil. ft ² >7,800 to 780,000 acres	>34 billion ft ² >780,000 acres	ft ² ÷ 34,000 acres ÷ 0.78
	Pile	≤1,300 ft ² ≤0.029 acres	>1,300 to 130,000 ft >0.029 to 2.9 scres	> 130,000 to 13 million ft ² 2.9 to 290 acres	> 13 million ft ² > 290 acres	$ft^2 \div 13$ acres ÷ 0.00029
	Land treatment	≤27,000 ft ² ≤0.62 acres	> 27,000 to 2.7 million ft ² > 0.62 to 62 acres	2.7 mil. to 270 million ft ² 62 to 6.2000 asres	>270 million ft ² >6,200 acres	ft ² ÷ 270 acres ÷ 0.0062


 $1 \text{ ton} = 2,000 \text{ ibs} = 1 \text{ yd}^3 = 4 \text{ drums} = 200 \text{ gallons}$


SI TABLE 2: HWQ SCORES FOR MULTIPLE SOURCE SITES

Site WQ Total	HWO Score
0	0
1 ^a to 100	1 ^b
> 100 to 10,000	100
>10,000 to 1,000,000	10,000
>1,000,000	1,000,000


^aIf the HWQ total is between 0 and 1, round it to 1.


bIf the hazardous constituent quantity data are not complete, assign the score of 10.





Howe Richardson Scale Co. (former) CERCLIS No. VTD002078509 21 September 1998





GROUNDWATER PATHWAY

Pathway Description and Scoring Notes: Describe the Groundwater Migration Pathway Include the names and brief descriptions of the aquifers underlying the site, the depth to groundwater, the locations of the nearest private and public drinking water supplies and the aquifers from which they draw, and the population relying upon groundwater drawn from within 4-radial miles of the site for their drinking water supplies.

Briefly discuss any sampling events relative to the Groundwater Pathway; provide dates of sampling events and a summary of the analytical results and whether an observed release and/or actual contamination targets were rocumented.

Indicate any assumptions you have made in scoring the Groundwater Pathway for this site, of any key factors which influence your scoring rationale.

The surficial geology in the vicinity of Rutland, Vermont consists of glacial lacustrine deposits or recent alluvial material [1]. According to seismic data and drilling records by FT, these deposits consist of approximately 100 feet of till material overlain by an average of 67.5 feet of silt and clay. These deposits are covered by lake sand and alluvium [1].

FT excavated three test pits and advanced 16 soil borings during their 1986 EC. Soil borings were advanced to a maximum depth of 40 feet below the ground surface. The maximum depth of the test pits was 18 feet. According to FT, the soil borings and test pits indicate that the Howe property primarily consists of silty clays and clayer silty. The southern portion (landfill) of the property has been filled with slag, cinder, and "miscellaneous plant refuse". Groundwater contour maps prepared by FT indicate that the on-site groundwater flows in a southeasterly direction, toward Moon Brook [1].

Bedrock in the vicinity of the Howe property has been mapped as Cambrian and Ordovician aged metamorphic quartzites, phyllites, schists, and dolomites [1]. No bedrock formation mapped within 4-radial miles of the Howe property is known to exhibit karst characteristics [40].

NUS/FIT noted that 13 monitoring wells and one recovery well were installed by DK in 1980. Monitoring wells were placed at tocations/believed to be downgradient from the alleged solvent disposal area. The former recovery well was installed as a response to a No. 6 fuel oil spill. Organic contaminants primarily chlorinated solvents, have been detected consistently in samples collected from on-site monitoring wells. During a 1980 landfill investigation by DK, heavy metals such as lead, chromium, and sinc were found in groundwater. Additionally, the PA stated that the elevated land north of Moon Brook appeared to be a former landfill area used for the disposal of foundry as less and wastes.

Groundwater measurements range from an average of 2.68 to 19.83 ft at MW-PZ-2B to MW-WC-2S, respectively.

Quarterly groundwater monitoring by ATC across the Howe property from October 1989 to July 1997 revealed the presence of the following compounds in the following monitoring wells at the following maximum concentrations in parts per billion (ppb): chloroethane [MW-4B] (83); carbon tetrachloride [MW-4B] (21); total xylenes [MW-4B] (21.4); lead [MW-35] (28); benzene [PZ-1B] (24); dichlorobenzene [PZ-1B] (3,200); 1,3-dichlorobenzene [PZ-1B] (240); 1,4-dichlorobenzene

GROUNDWATER PATHWAY (Continued)

[PZ-1B] (114); 1,1,1-trichloroethane [MW-30] (1,300); 1,1-dichloroethane [MW-31D] (1,090); 1,1-dichloroethylene [MW-32S] (1,000); 1,2-dichloroethylene [MW-32S] (220); trichloroethylene [MW-36D] (5,800); 1,2-dichloroethylene [MW-37S] (44.9); methylene chloride [WC-1-S] (260). These compounds were detected in monitoring wells MW-4B, MW-30, MW-31-D, MW-32-S, MW-35, MW-36-D, MW-37-S, PZ-1B, and WC 1-S.

Vermont towns located within 4-radial miles of the Howe property include Rusland, Clarendon, Mendon, Proctor, Shrewsbury, and West Rutland [36; 37; 38; 39]. Proctor and Shrewsbury do not have public water supplies located within 4-radial miles of the Howe property [22; 23]. Thirteen public water supply wells are located within 4-radial miles of the Howe property, within the Towns of Rutland, West Rutland, and Clarendon [26].

Rutland is organized into three different villages: the City of Rutland, the Town of Rutland, and Center Rutland. The residents of the City of Rutland are served by the Rutland City Reservoir, located approximately 4.5 miles north of the Howe property and not on the 15-mile downstream surface water pathway [19]. Part of the Town of Rutland and Center Rutland are also supplied drinking water by the Rutland City Reservoir [20].

The Town of Rutland contains stx groundwater drinking water supply wells located within 4-radial miles of the Howe property: Town of Rutland Water System (0.9 miles southwest); Grandview Acres (1.5 miles northeast); Killington Heights (1.75 miles east); Mountain View Estates (2.1 miles northeast); and Colonial Estates Water Corporation (3.75 miles northeast). These wells serve approximately 30, 125, 148, 56, and 150 people, respectively.

Center Rutland residents are supplied with groundwater from two fire district drinking water supply wells [9; 23]. Fire District No. Lis located in the City of Rutland 2.0 miles southwest of the Howe property and serves approximately 500 people. Fire District No. 4 is located in the Town of Rutland 2.5 miles northeast of the Howe property and serves approximately 50 people.

The Town of West Rutland is supplied by two gravel-packed wells located on Fairview Road, approximately 3.3 miles southwest of the Howe property. These wells are located within 50 feet of each other and are considered one groundwater supply source. There are 700 households (approximately 2,500 people) served by the wells. The rest of the population is supplied by private drinking water supply wells [18].

The Town of Clarendon maintains two public drinking water supply sources, identified as Terrace Hills (spring) and the Coburn Mobile Home Park (bedrock well), located within 4-radial miles of the Howe property [16; 23]. Terrace Hills, 2.75 miles southwest, and Coburn Mobile Home Park, 2.75 miles south, serve approximately 30 and 110 people, respectively.

Rocky Ridge Home Owners, located 2.25 miles east in Mendon, supplies drinking water to an estimated 110 people. East Mountain Water Corporation, 2.5 miles northeast, is also located in Mendon, supplying an estimated 42 people with drinking water. The following table summarizes public groundwater supply sources within 4-radial miles of the Howe property.

GROUNDWATER PATHWAY (Continued)

Public Groundwater Supply Sources Within 4-Radial Miles of Howe Richardson Scale Co. (former)

~				
Distance/ Direction from Site	Source Name	Location of Source	Estimated Population Served	Source Type ^b
0.9 miles SW	Town of Rutland Water System	Town of Rutland	736	Bodrock
1.5 miles NE	Grandview Acres	Town of Rutland	125	Bedrock
1.75 miles E	Killington Heights	Town of Rutland	148	Bedrock
2.0 miles SW	Fire District No. 1	City of Rutland	500	Overburden
2.1 miles NE	Mountain View Estates	Town of Rutland	56	Bedrock
2.25 miles E	Rocky Ridge Home	Mendon	110	Bedrock
2.5 miles NE	East Mountain Water Corporation	Mendon	42	Bedrock
2.5 miles NE	Fire District No. 4	Town of Russiand	50	Unknown
2.75 miles SW	Tertace Hills	Clarendon	30 .	Spring
2.75 miles S	Coburn Mobile	Charendon	110	Bedrock
3.3 miles SW	West Ruyand Water Wells	West Rutland	2,500	Overburden
3.75 miles NB	Colonial Estates Water Corporation	Town of Rutland	150	Bedrock

^a Indicates Town in which well is located.

[9; 16; 18; 19; 20; 22; 44]

Private groundwater supplies within 4-radial miles of the property were estimated using equal distribution calculations of U.S. Census CENTRACTS data identifying population, households, and private water wells for "Block Groups" which lie within or partially within individual radial distance rings of the Howe property. The nearest private drinking water supply well is located within 0.25- to 0.5-radial miles of the property [11]. The following table summarizes estimated drinking water populations served by groundwater sources within 4-radial miles of the Howe property.

Howe Richardson Scale Co. (former) CERCLIS No. VTD002078509

b Overburden, Bedrock, or Unknown.

GROUNDWATER PATHWAY (Continued)

Estimated Drinking Water Populations Served by Groundwater Sources Within 4-Radial Miles of Howe Richardson Scale Co. (former)

Radial Distance from the Howe Richardson Scale Co. (former) (miles)	Estimated Population Served by Private Wells	Estimated Population Served by Public Wells	Total Estimated Population Served by Scoundwater Sources Within the Ring
≥ 0.00 to 0.25	/ 0 >		0
> 0.25 to 0.50	/ 3//>	/%>	3
> 0.50 to 1.00	48	36	84
> 1.00 to 2.00	539	773	1,312
> 2.00 to 3.00	982	398	1,380
> 3.00 to 4.00	1,916	\$ 650	3,666
TOTAL	2,588	3,857	6,445
	$\overline{}$	/ > \	

[9; 11; 16; 19; 20; 22; 44]

During the on-site reconnaissance/six of the 16 monitoring wells were opened. START personnel obtained a PID reading of 2.1 units above background from MW-32S. No other PID readings were recorded from the remaining five monitoring wells. The monitoring wells were locked and observed to be in good condition except for MW-WC2 (shallow), which would not open due to rust.

START did not perform groundwater sampling as part of the Howe property SI. Based on analytical results from previous monitoring well sampling events conducted at the Howe property and the surrounding area, groundwater beneath the property has been impacted by a release of hazardous substances which appears to be at least partially attributable to on-site sources. However, based on the location and proximity of the surrounding residential wells, no nearby drinking water sources are known or suspected to have been impacted by the release from on-site sources. To date, the installation of a (former) recovery well, the removal of two No. 6 fuel oil USTs, and the excavated 35 cubic yards (yd³) of contaminated soils were the only actions taken to address the release to groundwater.

Howe Richardson Scale Co. (former) CERCLIS No. VTD002078509

SI TABLE 4: GROUNDWATER OBSERVED RELEASE SUBSTANCES (BY AQUIFER)

Mobility equals 1 for all observed release substances. Note:

f	Sample ID	Hazardous Substance	Substance Concentration (ppb)	Bekgrd. ID.	Bckgrd. Conc.	Tox. × Mob. = Tox.	References
1	MW-4B (10/89)	Chloroethane	83 🕿	MW-PZ-2B	ND	1	4; 8
1	MW-4D (7/90)	Carbon tetrachloride	y/	MW-PZ-2B	ND	1,000	4; 8
\int	MW-B (1/93)	'Total xylones	21.4	MW-PZ-2B	ND	10	4; 8
0,000	MW-36 (10/92)	I,eag	28()	MW-PZ-2B	ND	10,000	4; 8
	MW-PZ-1B (7/92)	Benzepe	24	MW/PZ-2B	ND	100	4; 8
100000000	MW-PZ-1B (7/90)	1,2 Dichloropenzens	3,200	MW-PZ-2B	ND	10	4; 8
	MW-PZ-1B (1/92)	1,3-Dichlorobenzene	240	MW/PZ-2B	ND	NL	4; 8
conseq.	MW-PZ-1B (1/93)	1,4-Dichlorobenzene)/4 //	MW-PZ/2B	/ND/	10	4; 8
	MW-30 (7/94)	1,1,1-Trichloroethane	1,300	MW-PZ-2B	ND ·		4; 8
2000000	MW-31-D (7/95)	1,1-Dichloroethane	1,096/	MW-PZ-ZB	NT/		4; 8
	MW-32-S (7/94)	1,1-Dichloroethylene	1,000	MW-PZ-2B	NIX /	100	4:8
2000	MW-32-S (10/96)	1,2-Dichloroethane	220	MW-PZ-2B	/ND	100	48
	MW-36-D (5/97)	Trichloroethylene	5,800	MW-BZ-2B) ND	y /	4; 8
	MW-37-S (10/95)	1,2-Dichloroethylene	44.9	MW-PZ-2B	/ /ND /_	100	4; 8
L	MW-WC-1-5 (7/92)	Methylene chloride	260	MW-PZ-2B	/ ND/	70	4; 8

Notes: ND = Not detected.

ppb = Parts per billion.

Detection limit equals 5 ppb, with the exception of lead which has a detection limit of 2 ppb.

SI TABLE 5: GROUNDWATER ACTUAL CONTAMINATION TARGETS

Notes: Convert all results and SCDM values to ppb or μ g/L. If sum of percents calculated for I or J index is ≥ 100%, consider the well a Level I target; if sum of I or J index is < 100%, consider the well a Level II target. Level II: Well ID: Level I: References: Population Served: Benchmark Cancer Risk Conc. % of. RfD Conc. % of Cancer Hazardous Conc. (MQL or MCLG) Benchmark (J Index) % of RfD (I index) Risk Conc. Substance $(\mu g/L)$ Sample ID Dercent Sum of Percents SCDM Version: JUN96 Notes: No known groundwater actual contamination targets have been documented to

GROUNDWATER PATHWAY WORKSHEET Data Score Type LIKELIHOOD OF RELEASE OBSERVED RELEASE: If sampling data or direct observation support a release to the aquifer, assign a score of 550. Record observed release substances on SI 4: 8 Table 4. 2. POTENTIAL TO RELEASE: Depth to aquifer: 2.68 to 19.83 feet. If sampling data do not support a release to the aquifer, and the site is in kars terrain or the depth to aquifer is 70 feet or less, assign a score of 500; otherwise, assign a score of 340. Optionally, evaluate potential to release according to MRS Section 3.1.2. LR = 550 Data Refs **TARGETS** Score Type Are any wells part of a blended system? Yes If yes, attach a page to show apportionment calculations ACTUAL CONTAMINATION TARGETS: If analytical evidence indicates that 3. any target drinking water well for the agaifer has been exposed to a hazardous substance from the site, evaluate the factor score for the number of people served (SI Table 5). /people > Level I: 0 0 Total = Level II: POTENTIAL CONTAMINATION TARGETS: Determine 4. the number of people served by drinking water wells for the aquifer or everlying aquifers that are not exposed to a hazardous sobstance from the site; record the population for each 9: 10: distance category in Sl Table 6a or 6b. Sum the population values and multiply by 11; 19; 94.2 20: 22 Assign a score of 50 for any Level I Actual Contamination Targets for the aquifer or everlying aquifer. Assign a score of 45 if there are Level II targets buy no Level Margets. If no Actual Contamination Targets exist, assign the Nearest Well Score from St Table 62 or 6b. If no drinking water wells 18 11 exist within 4 miles, assign & WELLHEAD PROTECTION AREA (WHPA): If any source lies within or 6. above a WHPA or the aquifer, or if a groundwater observed release has occurred within a WHPA, assign a score of 20; assign 5 if neither condition applies but a WHPA is within 4 miles; otherwise assign 0. 5 10 RESOURCES: Assign a score of 5 if one or more groundwater resource applies; 7. assign 0 if none applies. Irrigation (Sacre minimum) of commercial food crops or commercial forage crops Watering or commercial livestock Ingredient in commercial food preparation Supply for commercial aquaculture Supply for a major or designated water recreation area, excluding drinking 5 water use 122.2 Sum of Targets T =

Notes: Resources value was assumed.

SI TABLE 6 (FROM HRS TABLE 3-12): VALUES FOR POTENTIAL CONTAMINATION GROUNDWATER TARGET POPULATIONS

SI Table 6a. Other	Than	Karst	Aquifers
--------------------	------	-------	----------


1		, , ,	·												_	
	POPULATION SERVED BY WELDS WITHIN DISTANCE CATEGORY															
Distance From Site	Pop.	Nearest Well (choose highest)	1 10		31 to	101 to 309	301 to	1001 10 3000	5001 to 100p00	10,001 to 30,000	30,001 to 180,000	100,001 to 300,000	300,001 to 1,000,000	1,000,001 to 3,000,000	Pop. Value	Ref.
0 to 1/4 mile	0	20	4/	17	53	194	7522	1,623	5/214	16,328	7 ₅₂ / ₁₃₇	163,246	521,360	1,632,455	0	11
> 1/4 to ½ mile	3	18	2		33	102	324	1,013	3233	10,192	32,325	101,213	323,243	1,012,122	2	11
> ½ to 1 mile	84	9	1	5	17/	52/	167	528	1,669	5,234	16,684	\$2,239	166,835	522,385	17	11
> 1 to 2 miles	1,312	5	0.7_	3	10	1 00 ·	94	294	939	2,939	9,385	29,38	93,845	293,842	294	11
> 2 to 3 miles	1,380	3_	0.5	2	.7	21	68	1212	678	2,122	6,778	21,222	67.717	212,219	212	11
> 3 to 4 miles	3,786	2	- 0.3	1	4	13	42	131	417	1,306	4,171	13,060	1,709	130,596	417	11
	·	1						7		/ /	1 .				I	i

[9; 10; 11; 19; 20; 22]

Nearest Well =

Notes:

Sum =



CERCLIS No. VTD002078509

SURFACE WATER PATHWAY

Pathway Description and Scoring Notes: Describe the Surface Water Migration Pathway. Identify the nearest source area with non-zero containment for the Surface Water Pathway and the location of the PPE. Include the length of the overland segment. Describe the in-water segment up to the target distance limit noting the stream flow characteristics of each teach and the locations of drinking water intakes, fisheries and sensitive environments along the 15-mile pathway.

Briefly discuss any sampling events relative to the Surface Water Pathway; provide dates of sampling events and a summary of the analytical results and whether an observed release and/or actual contamination targets were documented.


Indicate any assumptions you have made in scoring the Surface Water Pathway for this site, or any factors which influenced your scoring rationale.

Note: If a site has more than one watershed or has both overland/flood and groundwater to surface water migration potential, document each scenario and use the higher scoring vatershed/migration route to calculate the surface water migration pathway score. Provide a summary of the scores for all other watershed/migration routes.

The topography of the Howe property is flat with a slight slope to the south. Approximately 75% of the property is covered by impermeable material (i.e., building footprint and asphalt-paved areas) [4]. As a result, precipitation falling on the northern portion of the property is likely to migrate by overland flow rather than infiltrate into the subsurface. START personnel observed five catchbasins located on the northern portion of the property. According to Mr. Joseph Giancola, these catchbasins are connected to the numicipal sewer system. Overland flow for the northern portion (not redirected by catchbasins) and precipitation falling on the southern portion of the property are likely to migrate off site by overland flow and infiltrate into the subsurface. Runoff from the property travels south into Moon Brook, except from portions of the property located south of Moon Brook where runoff travels northwest. Moon Brook traverses the southeast portion of the property and bounds the property to the southwest [7].

The most upstream probable point of entry (PPE) into the surface water for overland flow originating from the property is the southeastern portion of the property where the most upstream point of the reach of Moon Brook is located (Figure 3). From the PPE, Moon Brook flows in a southeasterly direction for approximately 0.9 miles until it reaches Otter Creek [36; 37; 38; 39]. The average surface water flow rate of Moon Brook (1.6 cubic feet per second (cfs)) at the PPE was estimated by START personnel using measurements gathered by PJD, Inc. [26]. The surface water flow rate for Moon Brook (3.22 cfs) at the confluence with Otter Creek was calculated by multiplying the square mileage of the drainage basin area by the U. S. Geological Survey (USGS) estimating factor of 1.8 cfs per square mile. The remaining 14.1 miles of the 15-mile surface water pathway are comprised of Otter Creek. The 15-mile downstream surface water pathway ends 0.75 miles southeast of Smiths Pond in Pittsford, Vermont [36; 37; 38; 39].

Surface water flow rates for otter Creek, which were determined from two gaging stations located approximately 2.7 and 39.4 miles downstream from the PPE, were obtained from Water Resources Data New Hampshire and Vermont - Water Year 1995, published by the USGS. USGS gaging station number 04282000 is on Otter Creek approximately 1.8 miles downstream from the Moon Brook/Otter Creek confluence and has recorded a long term mean annual flow rate of 550 cfs [41]. USGS gaging station number 04282500 is on Otter Creek approximately 24.4 miles downstream of the 15-mile downstream surface water pathway terminus, and has recorded a long term mean



SURFACE WATER PATHWAY (Continued)

annual flow rate of 992 cfs [41]. The flow rates for Otter Creek were extrapolated to determine the approximate flow rate at the confluence with Moon Brook (538/cfs) and at the 15-mile downstream terminus (698 cfs), respectively. The following table summarizes surface water bodies, flow characteristics, and wetlands frontage for the 15-mile downstream surface water pathway.

Surface Water Bodies Along the 15 Mile Downstream Pathway from Howe Richardson Scale Co. (former)

Surface Water Body	Descriptor ^a <	Length of Reach (miles)	Flow Characteristics (cfs) ^b	Length of Wetland Frontage (miles)
Moon Brook	Minimal Stream	0 to 0.9	1.6 to 3.2	0.1
Otter Creek	Moderate to Large Stream	0.910-15	538 to 698	3.5

Minimal stream < 10 cfs. Small to moderate stream 10-100 cfs. Moderate to large stream > 100-1,000 cfs. Large stream to river > 1,000-10,000 cfs. Large river > 10,000-108,000 cfs. Very large river > 100,000 cfs. Coastal tidal waters (flow not applicable). Shallow ocean zone or Great Lake (flow not applicable). Moderate depth ocean zone or Great Lake (flow not applicable). Three-mile mixing zone in quiet flowing river 10 cfs or greater.

b Cubic feet per second.

[12; 26; 32; 33; 34; 35, 36, 37; 38; 39; 41]

There are no known surface water drinking water intakes used for public drinking water supplies along the 15-mile downstream pathway from the Howe property [28]. Otter Creek is considered to be a Rainbow Trout, Large and Smallmouth Bass, and Northern Pike fishery [14]. No sensitive environments were reported by the Vermont Department of Fish and Wildlife to exist along the 15-mile downstream surface water pathway [25]. There are approximately 0.1 miles and 3.5 miles of wetlands frontage along Moon Brook and Otter Creek, respectively [32; 33; 34; 35]. The nearest wetlands, with a frontage of approximately 0.1 miles, is located on Moon Brook, 0.75 miles from the PPE. The following table summarizes the sensitive environments located along the downstream pathway from the Howe property.

SURFACE WATER PATHWAY (Continued)

Sensitive Environments Along the 15-Mile Downstream Pathway from Howe Richardson Scale Co. (former)

Sensitive Environment Name	Sensitive Environment Type	Surface Water Body	Downstream Distance from PPE (miles)	Flow Rate at Environment (cfs) ^a
CWA	CWA	Moon Brook	0 0 0.9	1.6 to 3.2
Wetlands (0.1 miles)	Wetlands	Moon Brook	0.75 to 0-85	2.95 to 3.13
Wetlands (3.5 miles)	Wetlands	Otter Creek	2.9 to 15	552 to 698

^a Cubic feet per second CWA = Clean Water Act PPE = Probable Point of Entry

[12; 25; 32; 33; 34; 35]

START did not perform surface water pathway sampling as part of the Howe property SI. No other surface water pathway sampling is known to have been conducted for the Howe property. No Clean Water Act-protected water body, fisheries, or sensitive environments are known or suspected to have been impacted.

suspected to have been impacted.

SI TABLE 7: SURFACE WATER OBSERVED RELEASE SUBSTANCES

List all substances	that meet the criteria fo	r an observed release	to surface water; h	nowever do not elim	inate a substance fro	m this table if it ha	as a BCF of less than 50	00.	
Sample ID	Hazardous Substance	Substance Concentration	Bekgrd. ID.	Bckgrd. Conc.	BCF HRS Table 4-15	Toxicity × Persistence	Toxicity × Persis. × Bioaccum	Ecotoxicity × Persis. × Ecobioaccum	References
17									
	(-(-))		/	$\bigwedge \setminus$					
	$\setminus \bigcup$							•	
				 	Φ				
<u></u>		A + V //		$\frac{1}{}$	Highest Values				
	· •		$\nearrow \nearrow$	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		7. /			
Notes: No known	surface water observed	release substances h	ave been collected t	to day.	, * </td <td>'</td> <td></td> <td></td> <td></td>	'			
SI TABLE 8:	SURFACE WA	TER DRINKI	NG WATER	ACTUAL CO	NTAMINATIO	N TARGET			
•			(100 percent consider the	vintake 2 Level II t	arget.
Intake ID:	-	vel I: Level II:	Population Se		erences			<u> </u>	
	Hazardous	Conc.	Benchmark Conc. (MCL or	% of	(J Index)	1 /	Cancer Risk Conc.		Du a
Sample ID	Substance	(μg/L)	MCLG)	Benchmark	(J Index)	% of RfD/	(Lindex)	% of Car	ncer Risk Conc.
						igstyle igytyle igstyle igytyle		>	
				+		·	1 . / /		
								///	
			Highest Percent		Sum of Percents		Sum of Perco	ents	
SCDM Version: J Notes: No.known	UN96 surface water drinking	water actual contam	ination targets have	been collected to da	ate.			~//	
	<u>.</u>								

SURFACE WATER PATHWAY LIKELIHOOD OF RELEASE AND DRINKING WATER THREAT WORKSHEET LIKELIHOOD OF RELEASE -Refs OVERLAND/FLOOD MIGRATION Score OBSERVED RELEASE: If sampling data or direct observation support a release to surface water in the watershed, assign a score of 550. Record observed release substanges on SI Table 7. POTENTIAL TO RELEASE: Distance to surface water: 0 (feet) 2. If sampling data do not support a release to sorface water in the watershed, use the table below to assign a score from the table below based on distance to surface water and flood frequency. 500 Distance to surface water Distance to surface/water and: Site in annual or 10-yr floodplain Site in 100 yr floodplain 100 Site in 500 300 Site outside **á**plain 500 according to ARS Optionally, evaluate surface water potential to release Section 4.1.2.1.2 LR = 500

LIKELIHOØD OF RELEASE \ / \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		Data	
GROUNDWATER TO SURFACE WATER MIGRATION	Score	Туре	Refs
1. QBSERVED RELEASE: If sampling data or direct observation			
OBSERVED RELEASE: If sampling data or direct observation support a release to surface water in the watershed, assign a score			į
of 550. Record observed release substances on SI Table 7.		•	
01 350. Accord observed Ricase substances on St. Table 7.	1		1
NOTE: Evaluate groundwater to surface water migration only for a surface			1
water body that incets all of the following conditions:	1		
water body that incers an of the following conditions.			
1) A portion of the surface water is within 1 mile of site sources			
having a containment factor greater than 0.			
2) No aquifer discontinuity is established between the source and the			
above portion of the surface water body.			
The top of the uppermost aquifer is at or above the bottom of the			
surface Water.			
Elevation of top of uppermost aquifer:			
Elevation of bottom of surface water body:	NE		
2. POTENTIAL TO RELEASE: Depth to aquifer: 2.68 to 19.83		·	
feet. If sampling data do not support a release to the aquifer, and			
the site is in karst terrain or the depth to aquifer is 70 feet or less			ļ
assign a score of 500: otherwise assign a score of 340. Optionally,			
evaluate potential to release according to HRS Section 3.1.2.	500	_	
		· · · · · · ·	•
	500		

Notes NE = Not evaluated.

Alternate Scenario: If sediment sampling data or direct observation support an observed release of a substance with a BCF ≥ 500, the likelihood of release value increases to 550.

SURFACE WATER PATHWAY LIKELIHOOD OF RELEASE AND DRINKING WATER THREAT WORKSHEET (Continued)

			(Cont.	inucu)				
DDD		TOTAL STATE OF A D	CETS		•	5-/	Data	Dog
DKIN	KING WATER	IHREAI IAK	GEIS	<u> </u>		Score	Туре	Refs
Reco	ord the water body	y type, flow, and	i number of peop	ole served by each	h i		$V \setminus V$	/
drink	cing water intake	within the distan	nce limit in the w	atershed. If the	re is	. \		
no d	rinking water inta	ake within the tar	rget distance lim	it, assign 0 to fac	ctors /	\ \	(()	
3, 4,	and 5.		/ ^		V_{λ}		$ \setminus \rangle$	
					, /)[\	\ ^	
		Water Body	^>	People	V /I		/	
	Intake Name	Туре	/Flow	Served		`	Y	
	No Intakes		V = V = V				,	
		<						
	•			, \	\setminus $ $	•		
			_ \ /	/	\backslash			·
Are a	ny intakes part of	a blended system	m? Yes N	- 	_ }	7	:	
If yes	, attach a page to	show apportion	ment calculations		-1			
3. AC	TUAL CONTAI	MINATIONTA	RGETS: If anal	ytical evidence				
ind	icates a drinking	water intake has	been exposed to	hazardous	>			
sub	stance from the	site, list the intal	ce name and eva	hate the factor s	eore			
for	the drinking wat	er population (S	I Kable 81.	~ // /	l			
		/)	> ' \					
	vel I: <u>Q</u> peop	ole 10=	<u> </u>	\		_		
Le	vel II: 0 peor	$ole \times 1 = $	0	Total	1 =	0	+	28
4. PC	TENTIAL CON	MOITAMINATION	TARGETS: De	termine the numi	ber of			
	ople served by dr							
	en exposed to a k							
po	outation values fr	om Si Table 9.	Sum the values	and multiply by (0.1.	0		
·F NIE	A DESCRIPTATE		50	/ Lovel I Assuel				
	AREST INTAKI				SCOTE			
	45 if there are							,
	no Actual Contam						1	
for	the intake neares	st the PPE from	SI Table 9. If n	o drinking water				
	akes exist, assign					0		
6. RE	SOURCES: Ass	sign a score of a	one or more s	surface water res	ource			
ap	olies; assign 0 if) > af aamamaasi	l food among on				
•		(5-acre minimum ial torage crops	in) of commercia	ii iood crops or	Į			
		of commercial l	ivestock	•	1	•		
•		in commercial		, L				
•				, excluding drink	ing			
	water use	1 -				5		
	(.)	1	Ç,	ım of Targets	T =	5		
Notes:	Resources value	was assumed	.50	an or rangets	. – L		1	
1000	Ticaparous varue	, as assumou.						

SI TABLE 9 (FROM HRS TABLE 4-14): DILUTION-WEIGHTED POPULATION VALUES FOR POTENTIAL CONTAMINATION FOR SURFACE WATER MIGRATION PATHWAY^(a)

		, ,			N	UMBER	OF PEOP	LE			
Type of Surface Water Body(b)	Pop.	Nearest Intake	10	11 to 30	31 to 100	101 to 300	301 to 1,000	1,001 to 3,000	3,001 to 10,000	10,001 to 30,000	Pop. Value
Minimal Stream (< 10 cfs)	\ 0	20/	/\4) R	53	164	522	1,633	5,214	16,325	0
Small to moderate stream (10 to 100 cfs)	/%	2	0.4	$\left \right ^{2}$	5	16	52	163	521	1,633	0
Moderate to large stream (> 100 to 1,000 cfs)	1//	6	0.04	97.92	0.5	2	5	16	52	163	0
Large Stream to river (>1,000 to 10,000 cfs)	X y	7	0,804	0.02	0.05	8.2	0.5	2	5	16	0
Large River (> 10,000 to 100,000 cfs)	.0	6/	/ %	0.002	0.005	0.02	0,05	C02	0.5	2	0
Very Large River (>100,000 cfs)	0	~<	4		0.001	0.002	Q.095	0.02	005	0.2	0
Shallow ocean zone or Great Lake (depth < 20 feet)	0	0	0	0/002	0.005	9.02	0.05	0.2		2	0
Moderate ocean zone or Great Lake (Depth 20 to 200 feet)	0	0	0	0.	0.00	0.002	0.005	9,02	0.05	0.2	0
Deep ocean zone or Great Lake (depth > 200 feet)	0	0	0	0	0	0.001	0.003	0.008	0.03	0.08	> °
3-mile mixing zone in quiet flowing river (≥ 10 cfs)	0	10	2	9	26	82	261	817	2,807	8,163	/

SI TABLE 9 (FROM HRS TABLE 4-14): DILUTION-WEIGHTED POPULATION VALUES FOR POTENTIAL CONTAMINATION FOR SURFACE WATER MIGRATION PATHWAY^(a) (Continued)

Type of Surface Water Body			30,001:	NU	MBER OF P	EOPLE		•
			20 001 ·					
		Pop.	to 100,000	100,001 to 300,000	300,001 to 1,000,000	1,000,001 to 3,000,000	3,000,001 to 10,000,000	Pop. Value
Minimal Stream (10 cfs)		0	52,137	163,246	521,360	1,632,455	5,213,590	. 0
Small to moderate stream		\bigcirc	5 214	16,325	52,136	163,245	521,359	0
Moderate to large stream (> 100 to 1,000 cfs)	_		(S) /	1,633	5,214	16,325	52,136	0
Large Stream to river (>1,000 to 10,000 cfs)	\nearrow		52	163	521	1,632	5,214	0
Large River (> 10,000 to 100,000 cfs)			$\sum_{i=1}^{N}$	$\left\langle \stackrel{\cancel{b}}{\leq} \right\rangle$	[] 5/2	163	521	0
Very Large River (>100,000 cfs)	/		9.5	1	J_ 5	764	52	0
Shallow ocean zone or Great Lake (depth < 20 feet)		0	\\ _{\}	/\$\rightarrow{\gamma}{\gamma}	52	163	\ \\\\ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	0
Moderate ocean zone or Great Lake (Depth 20 to 200 feet)		0	/o./	$\frac{1}{2}$	5	\ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	52	0
Deep ocean zone or Great Lake (depth > 200 feet)		0	0.3	\searrow_1	3	\ \ \ \	26	0
3-mile mixing zone in quiet flowing river (≥ 10 cfs	s)	0	26,068	81,623	260,680	8/6,227	2,606,795	0

^a Round the number of people to nearest integer. Do not round the assigned dilution-weighted population value to nearest integer

Treat each lake as a separate type of water body and assign it a dilution-weighted population value using the surface water body type with the same dilution weight from HRS Table 4-13 as the lake. If drinking water is withdrawn from coastal tidal water or the ocean, assign a dilution-weighted population value to it using the surface water body type with the same dilution weight from HRS Table 4-13 as the coastal tidal water or the ocean zone.

SI TABLE 10: HUMAN FOOD CHAIN ACTUAL CONTAMINATION TARGETS FOR WATERSHED

Convert all results and SCDM values to µg/kg or ppb. Notes: If sum of percents calculated for I or J index is ≥ 100%, consider the fishery a Level I target; if sum of I or J index is < 100 percent consider the fishery a Level II target. List only those substances that meet the observed release criteria in a fishery within the target distance limit and have a BCF of ≥ 500: BCF values are found on SI Table 7. Sample Type: Level II: Level I: References: % of Cancer Risk Cancer Conc Benchmark % of RfD Conc. Risk Sample ID Hazardous Substance (µg/kg Cond (FDAAL) Benchmark (J index) % of RfD (I index) Conc. Highest Percent Sum of Percents Sum of Percents Notes: No known human food chain actual contamination targets for watershed have been collected to date. SI TABLE 11: SENSITIVE ENVIRONMENT ACTUAL CONTAMINATION TARGETS FOR WATERSHED Convert all results and SCDM values to $\mu g/L$ or ppb. Notes: If the highest % of benchmark calculated is > 100%, consider the sensitive env. Level target; if the highest % of benchmark calculated is < 100% consider the sensitive env. a Level II target. Sample Type: Environment Value: **Environment ID:** Benchmark Conc. Conc. % of (AWOC of AALAC Benchmark Sample ID Hazardous Substance $(\mu g/L)$ References Highest Percent SCDM Version: JUN96 Notes: No known sensitive environments actual contamination targets for watershed have been documented to date.

SURFACE WATER PATHWAY (Continued) HUMAN FOOD CHAIN THREAT WORKSHEET

Data **K**efs **HUMAN FOOD CHAIN THREAT TARGETS** Score Record the water body type and flow for each fishery within the target distance limit. If there is no fishery within the target distance limit, assign a score of 0 at the bottom of this page. Water Body: Minimal Stream Fishery Name: Moon Brook Flow:).6 to 3.22 cfs Species: Unknown Production: lbs/yr Fishery Name: Otter Creek Water Body: Mod. to Lg. Stream Flow \$38 to 698 cfs Production: lbs/yr Species: Unknown FOOD CHAIN INDIVIDUAL (Select highest value) ACTUAL CONTAMINATION FIGHERIES: 7. Assign 50 points for a Level I fighery only if issue samples document an observed release of a substance with a BCF to a fishery within the target distance limit (SI Table 10) List substance(s): Assign 45 points for a Level II fishery if surface water/sediment samples document an observed release of a substance with a BCF \geq 500 to a fishery within the target distance limit (SI Table 10). List substance(s): 8. POTENTIAL CONTAMINATION Assign 20 points for a potential fishery in there is an observed release of a substance with a BCP > 500 (St Table 7) to a watershed containing fisheries within the target distance limit, but no Level or Level if fisheries are scored because there is no fishery documented between the PPE and the most downstream observed release sample point. If there is no observed release of a substance with a BCF ≥ 500 to a watershed) assign a value for potential contamination fisheries from the table below using the lowest flow of all fisheries within the target distance limit. FCI Value Lowest Flow 20 < 10 cfs 2 10 to 100 cfs 0 > 100 cfs, coastal tidal waters. oceans, or Great Lakes 10 3-mile mixing zone in quic flowing river FCI Value = 20 T =20 **Targets**

Notes: Alternate Scenario: If sed ment sampling data or direct observation support an observed release of a substance with a BCF > 500, and Level II Human Food Chain targets, the targets value increases to 45...

Howe Richardson Scale Co. (former) CERCLIS No. VTD002078509 .



When measuring length of wetlands that are located on both sides of a surface water body, sum both frontage lengths. For a sensitive environment that is more than one type, assign a value for each type.

ENVIRONMENTAL THREAT TARGETS	Score	Type	Refs
Record the water body and flow for each surface water sensitive environment within the target distance limit (see SI Table 12). If there is no sensitive environment within the target distance limit assign a score of 0 at the bottom of the page.	\bigtriangledown		
Environment Type (SI Table 13) Water Body Name	\		
Clean Water Act Wetlands (0.1 miles) Wetlands (3.5 miles) Minimal Stream Minimal	\searrow	,	
9. ACTUAL CONTAMINATION SENSITIVE ENVIRONMENTS: If sampling data or direct observation indicate any sensitive environment has been exposed to a hazardous substance from the site, record this information on SI Table 11, and assign a factor value for the environment (SI Tables 13 and 14).	/		į
Substance(s):		ľ	
From Table:			
Environment Type (SI Table 13) Environment Value (SI Multiplier (10 for Level 1) Tables 13 and 14) Product	:		
×			
			,
× =			
			•
Sum =	0		
10. POTENTIAL CONTAMINATION SENSITIVE ENVIRONMENTS:			
Flow (SI Table 12) Environment Type and Pot. (SI Table 12) Value (SI Tables 13 & 14) Cont. Product			
< 10 cfs 1 \times 5 (Clean Water Act) \times 0.1 = 0.5			
$< 10 \text{ cfs}$ \times 25 (0.1 mi. wetlands) \times 0.1 = 2.5			
> 100 to 1,000 cfs $0.01 \times 100 (3.5 \text{ mi. wetlands}) \times 0.1 = 0.1$		+	32; 35
Sum =	3.1		
Sum of Targets T =	3.1		

Notes: Alternate Scenario:

If sediment sampling data or direct observation support an observed release of a substance in SI Table 3 with Level 11 actual contamination sensitive environment targets (25 pts for 0.1 miles wetlands and 5 pts for WA), the targets value increases to 30.1.

Howe Richardson Scale Co. (former) CERCLIS No. VTD002078509 21 September 1998

SI TABLE 12 (HRS TABLE 4-13): SURFACE WATER DILUTION WEIGHTS

\	TYPE OF SURFACE WATER BODY	Plow Characteristics	Assigned Dilution Weight
	Minimal stream	< 10 cfs	1
	Small to moderate stream	10 to 00 cf:	0.1
X	Moderate to large stream	> 100 to 1,000 cfs	0.01
	Large stream to river	> 1,000 to 10,000 cfs	0.001
	Large river	10,000 to 100,000 cfs	0.0001
	Very large river	> 100,000 cfs	0.00001
	Coastal tidal waters	Flow not applicable; depth not applicable	0.0001
	Shallow ocean zone or Great Lake	Flow not applicable; depth less than 20 feet	0.0001
	Moderate depth ocean zone or Great Lake	Flow not applicable, depth 20 to 200 feet	0.00001
	Deep ocean zone or Great Lake	Flow not applicable; depth greater than 200 feet	0,000005
	3-mile mixing zone in quiet flowing river	10 cfs or greater	0.5

^{*} Check all () appropriate dilution weights.

Notes:

SI TABLE 13 (HRS TABLE 4-23):

SURFACE WATER AND AIR SENSITIVE ENVIRONMENTS VALUES Assigned Value ė Sensitive Environment 100 Critical habitat for Federal designated endangered or threatened species Marine Sanctuary National Park Designated Federal Wilderness Area Ecologically important areas identified under the Coastal Zone Wilderness Act Sensitive Areas identified under the National Estuary Program or Near Coastal Water Program of the Clean Water Act Critical Areas identified under the Clean Lakes Program of the Clean Water Act (subareas in lakes or entire small lakes) National Monument (air pathway only) National Seashore Recreation Area National Lakeshore Recreation Area threatened species 75 Habitat known to be used by Federal designated or proposed endangered of National Preserve National or State Wildlife Refuge Unit of Coastal Barrier Resources System Coastal Barrier (undeveloped) Federal land designated for the protection of natural ecosystems
Administratively Proposed Federal Wilderness Area

Spawning areas critical for the maintenance of fish/shellfish species within a river system, bay or estuary
Migratory pathways and feeding areas critical for the maintenance of
anadromous fish species within river reaches or areas in lakes or coastal
tidal waters in which the fish spend extended periods of time Terrestrial areas utilized by large or dense aggregations of vertebrate animals (semi-aquatic foragers) for breeding
National river reach designated as recreational Habitat known to be used by State designated endangered or threatened species 50 Habitat known to be used by a species under review as to its Federal endangered or threatened status Coastal Barrier (partially developed)
Federally designated Scenic of Wild River State land designated for wildlife or game management 25 State designated Scenic or Wild R State designated Natural Area important to maintenance of unique biotic communities Particular areas, relatively small in size, State designated areas for the protection and maintenance of aquatic life under the Clean Water 5 Act arface Water Pathway) or SI Table 23 (Air Pathway)

See SI

Table

Wetlands


SI TABLE 14 (HRS TABI SURFACE WATER WETLANDS FRONTAGE VALUES

	*	TOTAL ZENGTH OF WETLANDS	ASSIGNED VALUE
\bar{\}		Dass than 0.1 mile	0
1	~	0.1 to 1 mile Greater than 1 to 2 miles	25 50
1		Greater than 2 to 3 miles Greater than 3 to 4 miles	75 100
)	Greater than 4 to 8 miles Greater than 8 to 12 miles	150 250
		Greater than 12 to 16 miles Greater than 16 to 20 miles	350 450
		Greater than 20 miles	500

eck (highest value for each applicable flow characteristic. lotes

potentially impacted by the site. *Check (✓) all environments impacted

RFACE WATER PATHWAY (Concluded) WASTE CHARACTERISTICS, THREAT, AND PATHWAY SCORE SUMMARY



SURFACE WATER PATHWAY THREAT SCORES

Threat (T)	Likelihood of Release (LR) Score	Targets (T)	Pathway Waste Characteristics (WC) Score (determined above)	Threat Score LR × T × WC 82.500
Drinking Water (DW)	500	5//	32 🔨	0.97 (Maximum of 100)
Human Food Chain (HFC)	500	20	56	6.79 (Maximum of 100)
Environmental (E)	500	7.1	1/1/20	1/88 (Maximum of 60)

Multiply LR by T and by WC. Divide the product by \$2,500 for each threat (T). Sum the threat scores to obtain the surface water pathway score for each watershed/migration route. Select the highest watershed/migration route score.

If the pathway score is greater than 100, assign 108

SURFACE WATER PATHWAY CALCULATION:

$$(IDWT + HFCT + ET) =$$

9.64

(Maximum of 100)

$$DW = (500 \times 5 \times 32) \div 82,500 = 0.97$$

HFC =
$$(500 \times 20 \times 56) \times 82,500 = 6.79$$

$$E = (500 \times 3.1) \times 100) \div 92,500 = 1.88$$

$$(0.97 + 6.79 + 1.88) = 9.64$$

Notes: Alternate Scenario:

It sampling data or direct observation supported an observed release to the surface water pathway, with Level II fishery and sensitive environment (CWA, wetland) targets:

$$DW = (550 \times 5 \times 32) \div 82,500 = 1.07$$

$$HFC = (550 \times 45 \times 56) \div 82,500 = 16.8$$

$$E = (550 \times 30.1 \times 100) \div 82,500 = 20.07$$

$$(DV + HFC + E) = (1.07 + 16.8 + 20.07) = 37.94$$

SOIL EXPOSURE PATHWAY

Pathway Description and Scoring Notes: Identify all areas of observed contamination. Indicate whether a resident population is associated with the site and characterize the area surrounding the site. Identify the nearby population and any terrestrial sensitive environments located within the target distance limit.

Briefly discuss any sampling events relative to the Soil Exposure Pathway; provide dates of sampling events and a summary of the analytical results and whether an observed release and/or actual contamination targets were documented.

Indicate any assumptions you have made in scoring the Soil Exposure Pathway for this site, or any key factors which influenced your scoring rationale.

Approximately 75% of the Howe property is covered by impermeable material (i.e., building footprint and asphalt-paved areas) [4]. START personnel observed shain-link fences and buildings enclosing the majority of the property. In addition to Moon Brook, railroad tracks on the north, east, and west further restrict access. The parcel is zoned industrial, and is bound by Moulthrop Avenue to the southeast, a business located at Porter Place to the south, a residence located on Park Street to the southwest, and by railroad tracks to the north, east, and west. There are no known terrestrial sensitive environments located on the property [25].

Various tenants on the property employ approximately 300 full-time personnel. The nearest residence is located approximately 150 feet west of the Howe property at 93 Strongs Avenue. No known schools or day care centers are located within 200 feet of observed contamination on the property. START personnel observed three classrooms in Building No. 3 (Castleton State College). These classrooms hold seminars for transient students and are not located within 200 feet of a source area. An estimated 10,288 people reside within 1-radial mile from the subject property.


Located in the center of Building No. 16, under the only car lift, was a floor drain. START personnel presume that this drain redirects flow to a flush effluent pipe located in the rear (west) of Building No. 16. START personnel also presume that this effluent pipe is the discharge pipe mentioned in the FY EC. START personnel estimated that 8 ft² of black, discolored soil was located near the effluent pipe [15]. In addition, a PID reading of 93 units above background levels within the first inch of soil was resorded [7]. The depth of contaminated soil is unknown, but is presumed to extend approximately 6 feet to the groundwater table. There was stressed vegetation located near and adjacent to the stained soil [7].

According to Peter Giancola, following the START on-site reconnaissance, Hank's Auto Repair closed and Building No. 16 was leased to another automobile repair shop [43]. He also stated that the floor drain and surfet (effluent) pipe were closed in place using cement grout. Mr. Giancola stated that regarding the floor drain "we will be contacting Mr. Charles Schwer of VT DEC regarding the stained area identified in the Draft SI report. We anticipate that we will work with VT DEC to remove soft in the stained area. It is likely that the soils will be poly-encapsulated on site in a secure area. The removal of these soils will be documented and reported to VT DEC"

[43].

SOIL EXPOSURE PATHWAY (Continued)


START did not perform surface soil sampling as part of the Howe property SIP. No surface soil sampling is known to have been conducted for the Howe property. Based on the available data no release of hazardous substances to surficial soils from on-site sources has been documented. Furthermore, based on the site observations and conditions, property access restrictions, and distance to nearest residence (approximately 150 ft), no impacts to nearby residential populations




SI TABLE 15a: SOIL EXPOSURE OBSERVED CONTAMINATION SUBSTANCES

Sample ID	Hazardous Substance	Substance Concentration	Bekgrd. I	D. Bekgre	d. Conc.	Toxici	ty	References
		:						
		$\overline{\lambda}$						
		/	$\overline{}$					
			\leftarrow					
	/ // \) /	Highe	est Toxicity _			
		, (-						
	posure observed contaminati		_ /	\sim				
	OILEXPOSURE X		_ /	1 1				•
otes: Convert all resu	olts and SCDM values to ug/kg	or ppb. If sum of pero	ont calculated for	or J index is 10	00% consider re	sidents Level I	targets; if sum of I	or J index is < 100
consider the res	sidents Level II targets	Level I:	// `	Level	NI:/ /	/\	Population:	
Residence 1D.	· X		(A) (T)	% of	 		% of Cancer Ri	inly.
Sample ID	Hazardous Substance	Conc. (µg/kg)	(J index)	R(D)	Cancer R	dex)	Conc.	Reference
						$^{\prime}$		
					7/\\			7
						/		
	<u> </u>				1 1		\checkmark	
	•	Su	ım of Percents	$ {}$	∠ Sum	of Percents		
Residence ID:		Level I:		\checkmark	Level II:	/ ^	Population:	
				•	Cancer Ris	k/ /		
Sample ID	Hazardous Substance	Conc. (µg/kg)	RfD (Index)	% of RfD	Conc. (Index)	/ /% of	Cancer Kisk Conc.	References
Daniple 1D			(Y /		и
							1/-/	<i>₩///</i>
<u> </u>	- L	.u s. makim . maki. dikum .da				.a.8 4688.6 <u>2</u>		Y
								<i> ///</i>
			£ D		Sum of Perce	ents	`	\mathcal{M}
		. 31	ım of Percents] Smill of Ferce	, inc	<u>:</u>	J ' (

LIKELIHOOD OF EXPOSURE	Score	Data Type	Refg
1. OBSERVED CONTAMINATION: If evidence indicates presence of observed contamination (depth of 2 feet or less), assign a score of 550; otherwise, assign a 0. Note that a likelihood of exposure score of 0 results in a soil exposure pathway score of 0.	· ·		\ \{\}
TARGETS	0	\bigvee	/
2. RESIDENT POPULATION: Determine the number of people occupying residences or attending school or day care on contaminated property and within 200 feet of areas of observed contamination (HRS section 5.1.3).) /)\		
Level I: 0 people \times $10 = 0$ Level II: 0 people \times $1 = 0$		<u> </u>	
3. RESIDENT INDIVIDUAL: Assign a score of 50 if any Level I resident population exists. Assign a score of 45 if there are Level II targets but no Level I targets. If no resident population exists (i.e., no Level I or Level II targets), assign 0 HRS Section, 5.1.3).		,	
4. WORKERS: Assign a score from the table below for the total number of workers at the site and exarby facilities and within areas of observed contamination associated with the site.			,
Number of Workers Score			
101 to 1,000 10			
>1,000	10	+	7
5. TERRESTRIAL SENSITIVE ENVIRONMENTS. Assign a value for each terrestrial sensitive environment (SI Table 16) in an area of observed contamination.			
Torrestrial Sensitive Environment Type Value			,
6. RESOURCES: Assign a score of lift any one or more of the following resources is present on arga of observed contamination at	0	+	25
the site; assign 0 if none applies. Commercial agriculture Commercial silviculture Commercial livestock production or commercial			
livestock grazing Sum of Targets T=	10	+	7
		_	



SI TABLE 3 (HRS TABLE 5-5): SOIL EXPOSURE PATHWAY TERRESTRIAL SENSITIVE ENVIRONMENT VALUES



SI TABLE 17 (HRS TABLE 5-6); ATTRACTIVENESS/ACCESSIBILITY VALUES

	. III IIII OII VEI VEEDE III OEED IIII II V	
*	AREA OF OBSERVED CONTAMINATION	ASSIGNED VALUE
٠	Designated recreational area	400
	Regularly used for public recreation (for example, vacant lots in urban area)	75
	Accessible and unique recreational area (for example, vacant lots in urban area)	75
	Moderately accessible (may have some access improvements for example, gravel road) with some public recreation use	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
	Slightly accessible (for example, extremely rural area with no road improvement) with some public recreation use	25
	Accessible with no public recreation use	10
1	Surrounded by maintained fence or combination of maintained fence and natural barriers	5 .
	Physically inaccessible to public, with no evidence of public recreation use	0

* Check () highest value.

SI TABLE 18 (HR\$ TABLE

VALUES	
TOTAL AREA OF THE AREAS OF OBSERVED CONTAMINATION (SQUARE FEET)	ASSIGNED VALUE
≤ to 5,000	5
> 5,000 to 125,000	20
>125,000 to 250,000	40
> 250,000 to 875,000	60
375,000 to 500,000	80
> 590,000	100

Notes: An estimated 8 ft² and 403,137 ft of potentially contaminated soil are associated with the effluent pipe and landfill, respectively. The estimated area of potentially contaminated soil for the landfill includes the 450 ft² associated with the surface

impoundment.

SI TABLE 19 (HRS TABLE 5-8):NEARBY POPULATION LIKELIHOOD OF EXPOSURE FACTOR VALUES

Area of	Attractiveness/Accessibility Factor Value											
Contamination Factor Value	100	75	50	25	10	5	0					
100	500	\$00	375	250	125	50	0					
80	500	375	250	125	50	25	0					
)so	375	250	125	50	25	5	0					
40	250	125	50	25	5	5	0					
20/	125	50/	25)	5	5	5	0					
5	/ ₅₀ \	25	5	15	5	5	0					

SI TABLE 20 (ERS TABLE 5-10) DISTANCE-WEIGHTED POPULATION VALUES

					М	DEBER O	PEOPL	E WITHIN	THE TRAV	EL DISTAN	CE CATEGORY			
Travel Distance Category (miles)	Pop.	0	1 to 10	11 to · 30	31 to 100	101 to 300	301 to 1,000	1,001	3,001 to 10,001	10,001 to 30,000	30,001 to 100,000	100,001 to 300,000	300,001 to 1,000,000	Pop. Value
Greater than 0 to 1/4	866	0	0.1	0.4	1.0	4	13	41	130	198	1,309	4,081	13,034	13
Greater than	2,129	0	0.05	0.2	0.7	2	7	20	65	204	652	2,641	6,517	20
Greater than 1/2 to 1	7,293	0	0.02	0.1	0.3	1	3	10	33	102	326	1,920	2 258	33

References: [11]

Notes:

SOIL ENOSURE PATHWAY WORKSHEET Concluded)

WASTE CHARACTERISTICS	Score
10. Assign the hazardous waste quantity score calculated for soil exposure	700
11. Assign the highest toxicity value from SI Table 15a.	
Substance(s):	<u> </u>
Value:	
From Table:	\7 ~
FIOIR Table.	* /
12. Multiply the toxicity and hazardous waste quantity scores. Assign the Waste Characteristics score	$\setminus \setminus$
from the table below:	\ ^
	
Product WC Score *	
>0 to <10	
≥10 to <100 2	
≥100 to <1,000	
≥1,000 to < 10,000 6	
≥10,000 to <1E +05	
21E+05 to 1E+06 18	
≥1/E+0/6-to < 1/E+09 32	
≥1E 07 to <1E+08 56	
1E+08 or greater 100	
WC =	0
RESIDEAT POPULATION THREAT SCORE:	
(Likelihood of Exposure, Question 1; Targets = Sum of Questions 2/3, 4, 6) LE × T × WC =	0
82,500	·
Notes: $(0 \times 10 \times 0) \div 82,500 \neq 0$	
NEARBY POPULATION THREAT SCORE:	
(Likelihood of Exposure, Question 7; Targets = Sum of Questions 8,9	0
82,500	<u> </u>
Notes: $(25 \times 7.6 \times 0) \div 82 \underbrace{500 - 0}$, , , , , , , , , , , , , , , , , , ,
SOIL EXPOSURE PATHWAY CALCULATION:	
Resident Population Threat + Nearby Population Threat =	0
	(Maximum of 100)
Notes:	
	•

AIR MIGRATION PATHWAY

Pathway Description and Scoring Notes: Describe the Air Migration Pathway. Identify the nearest potential receptors of airborne contaminants and the population residing within four miles of the site. Identify any sensitive environments located within the target distance limit.

Briefly discuss any sampling events relative to the Air Panway; provide dates of sampling events and a summary of the analytical results and whether an observed release and/or actual contamination targets were documented.

Indicate any assumptions you have made in scoring the Air Pathway for this site, or any key factors which influenced your scoring rationale.

Various tenants on the Howe property employ approximately 300 full-time personnel [7]. The nearest residence is located approximately 150 feet west of the Howe property at 93 Strongs Avenue. No known schools or day care centers are located within 200 feet of an area of observed contamination on the property. START personnel observed three classrooms in Building No. 3 (Castleton State College). These classrooms hold seminars for transient students and are not located within 200 feet of a source area. An estimated 23,904 people reside within 4-radial miles of the property [11]. The following table summarizes the estimated population within 4-radial miles of the Howe property.

Estimated Ropulation Within 4-Radial Miles of Howe Richardson Scale (co. (former)

Radial Distance from Howe Richardson Scale Co. (former) (miles)	Estimated Population
On a Source	300*
) 0.00 to 0.25	866
> 0.25 to 0.50	2,129
0.50/to 1/00/	7,293
> 1.80 to 2.00	9,031
2.00 to 3.00	2,199
> 3.00 to 4.00	2,386
TOTAL	24,204*

*Includes on-site workers

[11]

There are approximately 854.5 acres of wetlands within 4-radial miles of the Howe property [13]. Two State-endangered and one State-threatened species habitats are known to be located within 4-radial miles of the property [25]. The following table summarizes the sensitive environments located within 4-radial miles of the Howe property.


AIR MIGRATION PATHWAY (Continued)

Sensitive Environments Located Within 4-Radial Miles of Howe Richardson Scale Co. (former)

Radial Distance from Howe Richardson Scale Co. (former)	Sensitive Environments
On a Source	8 acres wedands
	Clean Water Act (CWA)
> 0.00 to 0.25	0 acres werlands
> 0.25 to 0.50	2 acres wehands
> 0.50 to 1.00	25 acres wetlands
> 1.00 to 2.00	147.5 acres wetlands
	One occurrence of State-endangered species One occurrence of State-threatened species
> 2.00 to 3.00	360 agres/weijands
3,00 to 4.00	320 acres wetlands
	One occurrence of State-endangered species
	\ \

[14]

No laboratory qualitative air samples are known to have been collected from the Howe property. Based on the available data, no release of hazardous substances to the ambient air from on-site sources is known or suspected to have occurred, and no impacts to nearby residential populations or sensitive environments are known or suspected.



SI TABLE 21a: AIR PATHWAY OBSERVED RELEASE SUBSTANCES

Cample ID	Hazardous Substance	Substance Concentration	Bckgrd. ID	Bekgrd. Conc.	Gaseous or Particulate	Tox. × Mob. = Tox	. Reference
		. :					
1	<u> </u>	/					
	1			<u> </u>	. I .		
Notes: Wo known air pa	athway observed release	substances have been	documented to gate.		Highest Valu	ue [
SI TABLE 21be	ATR PATHWAY	ACTUAL CO	NTAMINATIO	N TARGETS			
Note: Convert all re	sults and SCDM value	to μg/m³ or ppb.		<)))			
=	V //					s < 100% consider the tar	gets as Level !
Sample ID:			Level II:	Distance	from Sources (mi		
Hazardous Substanc	Conc. (μg/m³)	Toxicity/ Mobility	Befichmark Conc. (NAAOS or NESHAPS)	% of Benchmark	RfD %	of RfD Cancer Risk Conc. (J index)	% of Cancer Risk Conc.
· · · · · · · · · · · · · · · · · · ·		/ X/			77 K		
			())		$H \wedge \mathcal{A}$	>/(\	
	Highest Tox.		Highest Percent		Sum of	Sum of	
	× Mobility				Percents	Percents	<u></u>
				\\/.\/\		, , , , , , , , , , , , , , , , , , ,	
Sample ID:			evel II:	Distance	from Sources (mi);	Refere	
Hazardous Substan	Conc _s ce (μg/m³)	Toxicity/ C Mobility	Benchmark Conc. (NAAQS or NESHAPS)	% of Benchmark	RAD (Mindex) %	of RfD J index	% of Cancer Risk Conc.
				• .	. 4 /		$\overline{}$
							a)
200200000000000000000000000000000000000							11/
· · ·	Highest Tox. × Mobility		Highest Percent		Sum of Percents	Sum of Percents	
			. 4				7 /
Notes: No known air pa	athway actual contamina	tion targets have been	documented to date.			•	

AIR PATHWAY WORKSHEET			
LIKELIHOOD OF RELEASE	Score	Data Type	Refs
 OBSERVED RELEASE: If sampling data or direct observation support a release to air, assign a score of 550. Record observed release substances on SI Table 21. 	7		
 POTENTIAL TO RELEASE: If sampling data do not support a release to the air, assign a score of 500. Optionally, evaluate air nigration gaseous and particulate potential to release (HRS Section 6.1.2). 	500	\{	
LR=	500	Data	
TARGETS ///	Score	Туре	Refs
3. ACTUAL CONTAMINATION POPULATION: Determine the number of people within the target distance limit subject to exposure from a release of a hazardous substance to the air.			
Level I: 0 people $\times 10 = 0$ Level II: 0 people $\times 1 = 0$) .		• •
4. POTENTIAL TARGET POPULATION Determine the number of people within the target distance limit not subject to exposure from a release of a hazardous substance to the air using SITable 22. Sum the values and multiply	40.0		7
by 0.1.	49.9	+	7; 11
5. NEAREST INDIVIDUAL. Assign a score of 50 if there are any Level I targets. 'Assign a score of 45 if there are Level II targets but no Level I targets. If no Actual Contamination Population exists, assign the Nearest Individual score from SI Table 28.	20		
6. ACTUAL CONTAMINATION SENSITIVE ENVIRONMENTS: Sum the sensitive environment values (SI Table 13) and wetland acreage values (SI Table 23) for environments subject to exposure from the release of a hazardous substance to the air. Sensitive Environment Type			
7. POTENTIAL SONTAMINATION SENSITIVE ENVIRONMENTS: Use SI Table 24 to evaluate sensitive environments not subject to exposure from a release	0.924	+	13; 23
8. RESOURCES: Assign a score of 5 if one or more air resources applies within 1/2 mile of a source; assign a 0 if none applies • Commercial agriculture • Commercial silviculture	. 5		
Major or designated recreation area	-	 	
Notes: Resources value was assumed.	75.824	!	

AIR PATHWAY WORKSHEET (Concluded)

WASTE CHARACTERISTICS 9. If any Actual Contamination Targets exist for the air pathway, assign the calculated hazardous wasty quantity score or a score of 100, whichever is greater; if there are no Actual Contamination Targets for the air pathway, assign the calculated HWQ score for sources available for air migration. 10. Assign the highest air toxicity × mobility value from SI Table 21 (or SI Table 3. Carbon tetrachloride Substance(s): Trichloroethane.1.1.2-Value: 1.000 1,000 From Table: 3 11. Multiply the toxicity and hazardous waste quantity ssign the Waste Characteristic the table below: Produc > 0 to < 10

Multiply LR by T and by WC. Divide the product by 82,500 to obtain the air migration pathway score. If the pathway score is greater than 100 assign 100.

AIR MIGRATION PATHWAY CALCULATION:

$$\underline{LE \times T \times WC} = 82.500$$
8.27

WC =

(Maximum of 100)

18

Notes: $(500 \times 75.824 \times 18) + 82.500 = 8.27$

SI TABLE 22 (NROM HRS TABLE 6-17): VALUES FOR POTENTIAL CONTAMINATION AIR TARGET POPULATIONS

Δ							•									
		_					\sim N	UMBER (OF PEOPLI	E WITHIN	THE DISTAN	CE CATEG	DRY			
Fr	tance .	Pop.	Nearest Individual (hoose highest)	1 to 10	11 to 30	51 to 100	101	301 to 1000	1001 to \$000	3001 to 10,000	10,001 to 30,000	30,001 to 100,000	100,001 to 300,000	300,001 to 1,000,000	1,000,001 to 3,000,000	Pop. Value
On a sou	rce	300/	20	7	1	53	164	572	1,633	5,214.	16,325	52,137	163,246	521,360	1,632,455	164
0 to 1/4 r	mile	866	/ * /		7	E	41	131	408	1,304	4,081	13,034	40,812	130,340	408,114	131
> 1/4 to	⅓ mile	2,129	2	9/2	\0; <u>\</u>	7	<u> </u>	26	887	282	882	2,815	8,815	28,153	88,153	88
> ½ to	1 mile	7,293	L /	0.06	0.3		3	8	26/	163	1 61	834	2,612	8,342	26,119	83
> 1 to 2	miles	9,031	0	0,92	0.09	0.3	0.8	N. N.	\\\ \&	27	\/ ₈₃ /	266	833	2,659	8,326	27
> 2 to 3	miles	2,199	0	0.009	0.04	0.1	0.4		4	12	38	120 (375)	1,199	3,755	4
> 3 to 4		2,386	0	0.005	0.02	\$.97	0/2	0.7	/2	7	28/	18	229	Ž	2,285	2
	Nearest Indi		20								>~	/	$\overline{}$	\sum_{λ}	Sum =	499

*Score = 20 if the Nearest Individual is within 1/8 mile of a source; score = 7 if the Nearest Individual is between 1/8 and 1/4 raile of a source.

[7; 11] Notes:

Howe Richardson Scale Co. (former) CERCLIS No. VTD002078509

21 September 1998

SI TABLE 23 (HRS TABLE 6-18): AIR PATHWAY

SI TABLE 24: DISTANCE WEIGHTS AND CALCULATIONS FOR AIR PATHWAY POTENTIAL CONTAMINATION SENSITIVE ENVIRONMENTS


VALUES FOR WETLAND AREA	_	CO	<u>NTAMINATION</u>	SENSITIVE ENVIRONMENT	<u>rs</u>
* WETLAND AREA ASSIGNED VALUE		DISTANCE	DISTANCE WEIGHT	SENSITIVE ENVIRONMENT TYPE AND VALUE (FROM SI TABLES 13 AND 23)	PRODUCT
l acre 0] / \	Оп а Ѕоигсе	0.10	× 0 acres of wetlands (0)	0
1 to 50 acres 25		\		× Clean Water Act (5)	0.5
> 50 to 100 acres 75		0 to 14 mile	0.025	× 0 acres of wetlands (0)	0
> 100 to 150 asres 125				X	
> 150 to 200 acres 155)	×	
> 200 to 300 acres 250		to ½ mile	0.0084	× 2 acres of wetlands (25)	0.135
✓ > 300 to 400 acres					
> 400 to 500 acres 450		_ ` `		×	· · · ·
> 500 acres 500]	to 1 mile	0.0016	× 25 acres of wetlands (25)	0.04
		P // ~	~ ~ /	\times	
* Check (/) highest value.			V ~	× / / /	
•	•	1 to 2 miles	p1.0096	× 147.5 acres of westands (125)	0.0625
· ·			////	Loccurrence of A (50)	0.025
			$\langle / V \rangle$	× Loccurrence of B (50)	0.025
		2 to 3 miles	0.00023	× 300 acres of wetlands (350)	0.0805
•			. ~	* / / /	
) · ·
		3 to 4 miles	0.00014	× 320 acres of wenands (350)	0.049
				× 1 occurrence of A (50)	0.007
				×	/_/_
		> 4 miles	0	×	0
Notes: A - state-endangered species	·		·	Total Environments Score	0.994

B - state-threatened species

21 September 1998

		\wedge
SITE SCORE CALCULATION	S	8
GROUNDWATER PATHWAY SCORE (S _{GW})	26.07	679.65
SURFACE WATER PATHWAY SCORE (S _{sw})	9.64	9293
SOIL EXPOSURE PATHWAY SCORE (SSE)	0	$\bigvee \sim_0$
AIR PATHWAY SCORE (S _A)	8.27	68.39
SITE SCORE $ \sqrt{\frac{S_{GW}^2 + S_{SW}^2 + S_{SE}^2}{4}} $		14.50
COMMENTS:		
Alternate Scenario: If sampling data or direct observed II fishery and sensitive environment (CWA.	F - C /	

23.38.



WARNING!

EPA has determined that the HRS score of any site that is progressing towards listing on the NPL is confidential. Deliberations regarding scoring of listing issues, the site specific status, and HRS scores cannot be released or discussed with non-Agency persons. For additional guidance see the April 30, 1993 OSWER Directive 9320.1-11.

HOWE RICHARDSON SCALE CO. (FORMER) REFERENCES

- [1] Fluor Technology, Inc. Environmental Services. 1986. Environmental Characterization of the Howe Richardson Scale Co. (former) Site. April.
- [2] US EPA (U.S. Environmental Protection Agency). 1984. Preliminary Assessment, Howe Richardson Scale Co. (former). Site No. VTD 002078509. 17 Desember
- [3] PJD, Inc. 1984. Letter to Nancy Piligian (US EPA), RE: Groundwater Monitoring at Howe Richardson Scale Co. former), 10 December.
- [4] ATC Environmental, Inc. 1997. Quarterly Montaging Activities. July.
- [5] Howe Center, Ltd. 1997 Howe Center Tenant List. 24 September.
- [6] Panza, P. (START) 1998. Project Note, RE. Howe Richardson Scale Co. (former) Groundwater Level Calculation TDD No. 97-04-0015. 16 January.
- [7] START. 1997. Field Logbook for Howe Richardson Scale Co. (former) Site Inspection No. 00222-8. PBD No. 97-94-0015. 16 October.
- [8] Dennison Environmental Services, Inc. 1992/ Report No. 10, RE: Summary of Quarterly Monitoring Activities. 13 March.
- [9] Unistot, K. (START). 1997. Phone Conversation Record with Howard Burgess (Rutland City Hall), RE: Rublic Water Supplies for Rutland Fire District No. 1. TDD No. 97-02-0038. 17 April.
- [10] Vermont Department of Health, Division of Environmental Health. 1990. Vermont Public Water Systems List, February.
- [11] Frost Associates. 1997. CENTRACTS Data Report. Howe Richardson Scale Co. (former) TDD No. 97-94-0015. 30 July.
- [12] Panza, P. (START). 1998. Project Note, RE: Howe Richardson Scale Co. (former), Flow Rate Calculations of Otter Creek, and Moon Brook. TDD No. 97-04-0015. 19 January.
- [13] Panza, P. (START). 1998. Project Note, RE: Wetland Distribution and Frontage for Howe Richardson Scale Co. (former) TDD No. 97-04-0015. 22 January.
- [14] DeLorme Publishing Company. 1986. Vermont Atlas and Gazetteer. Undated.

HOWE RICHARDSON SCALE CO. (FORMER) REFERENCES (Continued)

- [15] Panza, P. (START). 1998. Project Note, RE: Howe Richardson Scale Co. (former) Calculation of Soil Contamination. TDD No. 97-04-0015. 5 January
- [16] Vermont Department of Health, Division of Environmental Health. 1990. Vermont Public Water Systems List. February.
- [17] Panza, P. (START). 1998. Project Note, RE: Howe Richardson Scale Co. (former) Area and Volume Calculation for Landfill. TDD No. 97,04-0015. 5 January.
- [18] Umstot, K. (START). 1997. Phone Conversation Record with Joe Skanza of the West Rutland Public Water Supply, RE: West Rutland Public Water Supply. TDD No. 97-02-0038. 22 April.
- [19] Umstot, K. (START). 1997. Phone Conversation Record with Allen Shelby of the Rutland Water Department, RF. Rutland Rublic Water Supply. TDD No. 97-02-0038. 17 April.
- [20] Umstot, K. (START). T997. Phone Conversation Record with Joe Zingale of the Town of Rutland, RE: Town of Rutland Public Water Supply. TDD No. 97-02-0038. 17 April.
- [21] Umstot, K. (START) 1997. Phone Conversation Record with Howard Burgess of the Rylland City Hall, RE: File District No. | Well. TDD No. 97-02-0038. 17 April.
- [22] Umstot, K. (START) 1997. Phone Conversation Record with Warren McCullough of the Proctor Water Supply, RE: Proctor Public Water Supply. TDD No. 97-02-0038. 21 April.
- [23] VT DEC (Vermont Department of Environmental Commission) Water Supply Division.
 1997. Map of Rutland Public Water Supply Source Protection Areas and Source
 Locations. 15 October.
- [24] NUS Corporation Field Investigation Team (NUS/FIT). 1984. Preliminary Assessment, Howe Rishardson Scale Co. (former). 27 December.
- [25] Vermont Department of Fish and Wildlife, Nongame and Natural Heritage Program. 1997 Project Note, RE: Rare Species and Significant Natural Communities. TDD No. 97-04-0013. 11 November.
- PID Inc. 1987. Evaluation of Environmental Conditions at the Howe Richardson Scale Co. (former). September.

HOWE RICHARDSON SCALE CO. (FORMER) REFERENCES (Continued)

- [27] Panza, P. (START). 1998. Phone Conversation Record with the Clerk at Rutland Tax Assessor's Office, RE: Zoning for Howe Richardson Scale Co. (former) property. TDD No. 97-04-0015. 23 January.
- [28] START. 1997. Draft Site Inspection Workshests, RE: Prostor Dunap. TDD No. 97-02-0035. 12 June.
- [29] Sax, N. 1984. <u>Dangerous Properties of Industrial Materials</u>, Fifth Edition. New York: Van Nostrand Reinhold Company, Inc. Page No. 5; 346-347.
- [30] Sax, N. 1984. <u>Dangerous Properties of Industrial Materials</u>, Seventh Edition. New York: Van Nostrand Reinhold Company, Inc. Page No. 104; 981.
- [31] Panza, P. (START). 1998. Project Note, RE: Effluent Pipe Volume for Howe Richardson Scale Co. (former) IDD No. 97-04-001s. 3 February.
- [32] US DOI (U.S. Department of interior) Fish & Wildlife Service. 1980. Ruland, VT. (Natural Wedlands Inventory Maps).
- [33] US DOI U.S. Department of Interior). Fish & Wildlife Service. 1980. West Rutland, VT (Natural Wetlands Inventory Maps).
- [34] US DOI (U.S. Department of Interior). Fish & Wildlife Service. 1980. Chittenden, VT. (Natural Wedlands Inventor) Maps).
- [35] US DOI (U.S. Department of Interior). Fish & Wildlife Service. 1980. Proctor VT. (Natural Wetlands Inventory Maps)
- [36] USGS (U.S. Geological curvey) 1961; 1980 Photorevised. Rutland, VT. (7.5-minute series topographic map).
- [37] USGS (U.S. Geological Survey) 1964; 1972 Photorevised. West Ruland, VT. (7.5-minute series topographic map).
- [38] USGS (U.S. Geological Survey) 1944. Proctor, VT. (7.5-minute series topographic map).
- [39] USGS (U.S. Geological Survey) 1964; 1972 Photorevised. Chittenden, VT. (7.5-minute series topographic map).
- USGS (U.S. Geological Survey) 1995. Groundwater Atlas of the United States Segment 12. Hydrologic investigations atlas 730-M.

HOWE RICHARDSON SCALE CO. (FORMER) REFERENCES (Concluded)

- [41] USGS (U.S. Geological Survey) 1995. 1995. Water Resources Data New Hampshire and Vermont Water Year 1995.
- [42] Bowen, B. (START). 1998. Phone Conversation with Peggy Cillo (Rutland Tax Assessors Office) RE: Tax Map Information. TDD No. 98-05-0035. June.
- [43] Howe Richardson Scale Co. (former) 1998. Letter form Peter W. Giancola, Project Manager of Giancola Construction Corporation and Vice President of Howe Center to Donald Smith (EPA) Comments to Draft Report. 2 August.
- [44] Panza, P. (START). 1998. Phone Conversation with Peter Talop (VT DEC Water Supply Division) RE: Country Side Estates Public Well. FQD No. 98-05-0035. 8 September.

